金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sm Ming Drive #02-18/19/20 Sin Ming AutoCity Singapore 575722 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : YP 9232 H

NOT Swithouth CIRY & Mirany Afu Painy Uday

No.: 32891

Date: 20-Apr-2023

Our Ref: 023212 (LONPAC) / THERESA PAGE: 1

CHANG TAI CHIANG HARDWARE PTE LTD

: 18-Apr-2023

Singapore

Accident Date

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER (2998CC) (2014) YN5558E 

1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	front bumper LH front bumper side garnish LH headlamp LH front signal lamp LH front reflector front grille front grille logo 'Fuso' emblem @ front panel LH front corner garnish LH front corner garnish clips +ve LH front corner garnish clips -ve LH wingmirror stay cap cover LH wingmirror stay inner cover	@ S\$ 6.00 @ S\$ 6.00	
1 pc	LH wingmirror stay		1 110.00 c
	LH wingmirror stay big		£ 85.00 c x
			2.350.00
		Add 15%:	352.50
			2.702.50

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

To putty and respray on affected portions.

4001 600.00 7001

800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Con't Page 2 ...
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

全興(獎)汽車私人有限公司 K. KIM HIN AUTO PTE LTD 160 Sm Ming Prive #02-18/19/20 See Ming AutoCity Singapore 575722 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

vehicle Insured: YP 9232 H

Our Ref : 023212

Page : 2 No. : 32891

To focus headlamps. To check front wiring and lighting operation.

30.00 20/

Total:

S\$ 4.132.50

Singapore Dollars Four Thousand One Hundred and Thirty Two and Cents Fifty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.