

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 24 May 2023

Preliminary Advice

Vehicle No	: SLZ4411S	Accident Date	: 04/05/2023
Make	: MERCEDES-BENZ C180	Policy No.	: SP2004970978-01
Assignment Date	: 23/05/2023	Excess	: S\$600.00
Date of Inspection	: 24/05/2023	Est. Duration of Repair	: 7
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.

Repairer's Estimate (Gross)	:S\$	24,426.80
Revised Amount	:S\$	769.10
Check Items (Estimated)	:S\$	21,926.70
Total	:S\$	22,695.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	21,010.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,990.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.