

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSG23005182/4gp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNH7485E

at Workshop m/s Cersmith

of _____

Insured: GD3134H

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$130k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1336

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 81723

Date / Time _____ Action / Instruction 22/11

1/5 @ 4600 Under \$18718.06, 80%

Veh No: SNH7485E Yr Regn: 24/11/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) Electric

Make: BYD E6 (ME-2) c.c. 70.0kw

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 22105 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LC0CE4DC0N0269994

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Chao yong

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. _____ D.O.I. 22/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : MER-TP

Lump Sum / I.B.I. (\$) 4600)

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: SNH7485E

MAKE & MODEL: BYD E6

DOA: 18.05.2023

CLAIM TYPE: TP CLAIM

Not Allowed
22/5/23
1/5 @ 4600/
The photo showing
3 days.

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER TOP	1	\$ 1,405.00	20/2e — 1350
REAR BUMPER BOTTOM	1	\$ 1,380.00	2e — 480
REAR BUMPER RETAINER LH	1	\$ 87.00	11 X
REAR BUMPER RETAINER RH	1	\$ 87.00	11 X
REAR BUMPER BRACKET LH	1	\$ 87.00	11 X
REAR BUMPER BRACKET RH	1	\$ 87.00	11 X
REAR BUMPER GRILLE BAR LH	1	\$ 85.00	11 X
REAR BUMPER GRILLE BAR RH	1	\$ 85.00	11 X
REAR BUMPER GRILLE BAR CENTER	1	\$ 124.00	R X
REAR REFLECTOR LH	1	\$ 198.00	11 X
REAR REFLECTOR RH	1	\$ 198.00	11 X
REAR REFLECTOR CENTRE	1	\$ 425.00	11 X
REAR END PANEL	1	\$ 852.00	R X
REAR END PANEL TOP GARNISH	1	\$ 287.00	11 X
REAR REINFORCEMENT	1	\$ 565.00	R X
REAR REINFORCEMENT BRACKET	2	\$ 352.00	11 X
SPARE TYRE SPONGE	1	\$ 247.00	11 X
SPARE TYRE HOLDER	1	\$ 425.00	11 X
FLOOR PANEL	1	\$ 324.00	11 X
THIRD BRAKE LAMP	1	\$ 327.00	11 X
WINDSCREEN	1	\$ 857.00	11 X
WINDSCREEN MOULDING	1	\$ 472.00	11 X
WIPER	1	\$ 135.00	11 X
WIPER MOTOR	1	\$ 575.00	11 X
TAILGATE	1	\$ 5,459.40	50/500 — 3201
TAILGATE LOCK	1	\$ 578.00	11 X
TAILGATE WEATHERSTRIP	1	\$ 373.00	11 X
TAILGATE HINGE	2	\$ 176.00	11 X
TAILGATE LAMP LH	1	\$ 458.00	11 X
TAILGATE LAMP RH	1	\$ 458.00	11 X
TAILGATE LOGO	1	\$ 108.00	11 X
TAILGATE EMBLEM 'BYD E6'	1	\$ 108.00	11 X — 60
TAILGATE CHROME MOULDING	1	\$ 345.00	11 X
TAILGATE INNER TRIM BOARD	1	\$ 358.00	11 X
TAILLAMP LH	1	\$ 783.00	11 X
TAILLAMP RH	1	\$ 783.00	11 X
TAILLAMP BRACKET LH	1	\$ 275.00	11 X
TAILLAMP BRACKET RH	1	\$ 275.00	11 X
TAILLAMP CHROME MOULDING LH	1	\$ 175.00	11 X
TAILLAMP CHROME MOULDING RH	1	\$ 175.00	11 X
		\$ 20,553.40	
	LESS 10%	\$ 2,055.34	
	SUB TOTAL	\$ 18,498.06	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	11 ✓

REAR NUMBER PLATE W/GARNISH	1	\$	90.00	11 X
REAR END PANEL TOP GARNISH CLIPS	1 SET	\$	50.00	11 X
REVERSE CAMERA	1	\$	480.00	11 X
REVERSE SENSOR	1	\$	480.00	500 X
REVERSE SENSOR HOLDER	1	\$	80.00	11 X
COMPANY STICKER	1	\$	200.00	11 X
JOINT SEALANT	1	\$	120.00	
SUB TOTAL		\$	1,550.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 150.00	20
REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	1	\$ 200.00	120
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	50
REMOVE AND REFIT REAR ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 200.00	11 X
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	400
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,200.00	600
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 200.00	30

SUB TOTAL \$ 3,270.00

GRAND TOTAL \$ 23,318.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5091
102
4581.9
50
1220
5851.9
212
4681