

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23005195/Tvp3e2	
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	30/05/2023	
	ATTN: KHOR SAW	THENG	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 8561D	Veh. Inspected	SME 2269Z	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S3M04MOB	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	23/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	ZWR800305138	Colour	BLACK	
	Odometer	425411 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MATRAX	6 mm	
	L/H Front Tyre	195/65 R15	MATRAX	6 mm	
	R/H Rear Tyre	195/65 R15	MATRAX	6 mm	
	L/H Rear Tyre	195/65 R15	MATRAX	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	REAR PORTION.		
5.	General Information				
	Accident Date	18/05/2023	Inspect Date / Time	23/05/2023 ( 04:15 PM )	
	Survey held at APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$6,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/HSB23005195/Tvp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.