

SNGAHTEE

MOTOR & PANEL SERVICE

孙亚弟汽车烧焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4 lines) FAX: 62681429 | www.sngahtee.com
sngahtee@singnet.com | UEN / GST REG. NO.: 200810440N

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #07-16 SINGAPORE 079120

ATTENTION:

CONTACT: 64193000

FAX NO: 68357416

EST/QUOTE NO. SQ008166

DATE 24/05/2023

ACCIDENT DATE : 22/05/2023

VEHICLE NO : SNH9266H

CHASSIS/ENG.NO : ZSU600077992

VEHICLE MODEL : TOYOTA HARRIER

CLAIM NO : CC6/AIG23005197/YA3

POLICY NO :

REMARK 9266 AIG TP AGST
SCZ6698A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER <i>de</i>	572.25	25	429.19	429.19
2	1	PC	FRT BUMPER LOWER GUARD <i>de</i>	581.90	25	436.43	436.43
3	1	PC	FRT BUMPER LWR SKIRT <i>ca</i>	561.60	25	421.20	421.20
4	<i>1/2</i>	PC	FRT BUMPER RETAINER LH/RH <i>ca</i>	172.25	25	129.19	258.38
5	1	PC	FRT BUMPER LOWER GRILLE <i>ca</i>	371.70	25	278.77	278.77
6	1	PC	FRT BUMPER TOW COVER LH <i>ca</i>	121.25	25	90.94	90.94
7	1	PC	FRT BUMPER SPONGE <i>de</i>	181.90	25	136.43	136.43
8	1	PC	FRT BUMPER REINFORCEMENT ?	571.10	25	428.32	428.32
9	1	PC	FRT BUMPER UPPER REINF ?	671.25	25	503.44	503.44
10	<i>1/2</i>	PC	FRT BUMPER SIDE BRACKET LH/RH <i>ca</i>	121.10	25	90.83	181.66
11	2	PC	FRT BUMPER SIDE SPONGE LH/RH ?	131.10	25	98.33	196.66
12	1	PC	FRT BUMPER UNDERCOVER ?	571.10	25	428.32	428.32
13	1	PC	FRT GRILLE ASSY ?	971.10	25	728.33	728.33
14	1	PC	FRT GRILLE TOP GARNISH <i>2x</i>	561.60	25	421.20	421.20
15	1	PC	FRT FOGLAMP LH ?	371.10	25	278.32	278.32
16	1	PC	FRT FOGLAMP COVER LH <i>ca</i>	182.10	25	136.57	136.57
17	1	PC	FRT FENDER INNERSHIELD LH ?	561.60	25	421.20	421.20
18	<i>1/2</i>	PC	FRT HEADLAMP LH/RH <i>ca</i>	2,721.10	25	2,040.83	4,081.66
19	1	PC	FRT SUPPORT TOP SIDE LH ?	571.80	25	428.85	428.85
20	1	PC	AIR INTAKE INLET ?	274.45	25	205.84	205.84

JOYCE

PAGE: 1 of 3

8%

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #07-16 SINGAPORE 079120

ATTENTION:

CONTACT: 64193000

FAX NO: 68357416

EST/QUOTE NO. SQ008166

DATE 24/05/2023

ACCIDENT DATE : 22/05/2023

VEHICLE NO : SNH9266H

CHASSIS/ENG.NO : ZSU600077992

VEHICLE MODEL : TOYOTA HARRIER

CLAIM NO : CC6/AIG23005197/YA3

POLICY NO :

REMARK : 9266 AIG TP AGST
SCZ6698A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	AIR INTAKE RESONATOR ?	281.90	25	211.43	211.43
22	1	PC	FRT FENDER LH <i>ben</i>	971.50	25	728.63	728.63
SUB-TOTAL:							11,431.77
** NETT PRICE **							
1	10	PC	FRT BUMPER CLIPS <i>ne</i>	4.00		4.00	30 40.00
2	10	PC	FRT GRILLE TOP GARNISH CLIPS ?	4.00		4.00	30 40.00
3	10	PC	FRT FENDER INNERSHIELD CLIPS <i>ne</i>	4.00		4.00	30 40.00
SUB-TOTAL							120.00
** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE <i>X</i>	45.00		45.00	45.00
SUB-TOTAL							45.00
** WORK LABOUR **							
TO KNOCK FRT BONNET, FRT DOOR LH, WELD,						850.00	500 850.00
REMOVE & REPLACE ABOVE PARTS						0.00	0.00
TO SPRAY PAINTING ON AFFECTED AREAS						1000.00	800 1,000.00
TO CHECK WIRING						30.00	30.00
TO DIAGNOSE & RESET FAULT CODE						180.00	100 180.00
TO DO WHEEL ALIGNMENT						80.00	60 80.00

JOYCE

PAGE: 2 of 3

8%

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING
78 SHENTON WAY #07-16 SINGAPORE 079120

ATTENTION :
CONTACT : 64193000 FAX NO: 68357416

EST/QUOTE NO. SQ008166

DATE : 24/05/2023
ACCIDENT DATE : 22/05/2023
VEHICLE NO : SNH9266H
CHASSIS/ENG.NO : ZSU600077992
VEHICLE MODEL : TOYOTA HARRIER
CLAIM NO : CC6/AIG23005197/YA3
POLICY NO :
REMARK : 9266 AIG TP AGST
SCZ6698A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO APPLY ANTI RUST COAT			120.00	120.00
						120.00	
						SUB-TOTAL	2,260.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Panel
hp 90010068
6 damp
L/S
24/05/23 @ 1330
Revy after repair

JOYCE

PAGE: 3 of 3

SUB-TOTAL : S\$ 13,856.77
ADD GST. 8% S\$ 1,108.54
GRAND TOTAL : S\$ 14,965.31

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.