

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/H5B23005199/4P23

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 2477J

at Workshop m/s 2nd Ave

of _____

Insured: SHA 8329A

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$15k.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMF 2477J Yr Regn: 28/07/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Wish c.c. 1794

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 207205 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W8*03003116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/05/23 D.O.I. 23/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Del 13k.

CORUM (27-07-2024) LTA 5049

30/5/23 4/5 & 4/100 in hand AH 100g

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

2nd Auto Ptd Ltd

Toyota Wish (SMF2477F)

ESTIMATE VEHICLE COST OF REPAIR

not Authorised
23/5/23
1/5 @ 4100/
5 days.

List Items		
No.	Description (Parts)	Cost of Repair
1	Rear Bumper Assy	\$1,200.00
2	Rear Bumper Retainers (1 set)	\$120.00
3	Rear Bumper Bracket (1 set)	\$120.00
4	Rear Bumper Reflector (1 set)	\$200.00
5	Rear Bumper Impact Absorber (1 set)	\$450.00
6	Rear Tail Lamp Assy LH	\$1,050.00
7	Rear Tail Lamp Assy RH	\$1,050.00
8	Rear Side Ventilator LH	\$100.00
9	Rear Side Ventilator RH	\$100.00
10	Rear Tailgate Assy	\$1,500.00
11	Rear Tailgate Lock Assy	\$450.00
12	Rear Tailgate Striker Assy	\$120.00
13	Rear Tailgate Lower Garnish Inner	\$320.00
14	Rear Tailgate Garnish Outer	\$220.00
15	Rear Tailgate Weatherstripe	\$250.00
16	Rear Windscreen Moulding	\$250.00
17	Rear Tailgate Inner Trim	\$580.00
18	Rear Fender Assy LH	\$1,200.00
19	Rear Fender Assy RH	\$1,200.00
20	Rear End Panel Assy	\$880.00
21	Rear Exhaust Pipe Mufflers	\$960.00
22	Rear Spare Tyre Brackets	\$350.00
Total Cost of List Parts		\$12,670.00

Special Nett Items		
No.	Description (Parts)	COST
1	Rear Bumper Clips (1 set)	\$120.00
2	Rear Vehicle Plate	\$220.00
3	Rear windscreen sealant	\$180.00
4	Rear Bumper Parking Sensors (1 set)	\$650.00
5	Rear Spare Tyre	\$180.00
Total Cost of Special Nett Items		\$1,170.00
TOTAL COST OF PARTS		\$13,840.00

Labour		
No.	Description (Parts)	COST
1	To cut, weld, straighten affected areas and replace damaged parts.	\$2,000.00
2	To putty and spray painting the affected areas.	\$2,000.00
3	To check rear lighting and wiring.	\$120.00
4	To apply anti rust proofing to the affected areas.	\$300.00
4	To remove and install rear windscreen to facilitate the repair.	\$250.00
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$200.00
6	To conduct vehicle full diagnosis and fault findings to facilitate the repair.	\$400.00
7	To conduct chassis alignment	\$250.00
Total Cost of Labour		\$5,520.00
TOTAL COST OF REPAIR		\$19,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3884.80
252
282/1
270
1960