

3FD 3301U
SMT 9P99E
GY 5F

TP 31/01/2023
TP 16/01/2023
No of Reports:
Number of Reports:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 20051400L

*NOT Not known
Accuracy B4 paint
Ex TBA
4-5 days*

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01, SUNTEC TOWER 3 SINGAPORE 038988

Estimate : OD23/017

Date : 20/05/2023
Vehicle Num. : SKK 88J
Make/Model : MERCEDES S450L-2017
Chassis/Eng# : WDD2221662A384160/27682430784697
Accident Date : 20/05/2023
Claim No. :
Reference : LYB/SKK88J/ERGO/OD/sl
Policy No. : DMPG23005338

Attention : Motor Claim Department
Contact : 68299199 Fax No. : 63338469

S/N	Quantity	Particular	Unit Price	Amount S\$
		PARTS PURCHASED :		
1.	1	FRONT BUMPER	1,580.00	1,580.00
2.	1	FRONT BUMPER RETAINER/RH	15.00	15.00
3.	1	FRONT BUMPER BRACKET/RH	15.00	15.00
4.	1	FRONT BUMPER INSIDE PART (SIDE)	317.00	317.00
5.	1	FRONT BUMPER SPONGE	191.00	191.00
6.	1	FRONT BUMPER TOWING COVER/RH	61.00	61.00
7.	1	FRONT BUMPER LOWER GRILLE/RH	121.00	121.00
8.	1	FRONT BUMPER LOWER GRILLE CHROME/RH	163.00	163.00
9.	1	FRONT BUMPER LOWER GRILLE/CENTRE	111.00	111.00
10.	1	FRONT BUMPER LOWER GRILLE CHROME/RH	161.00	161.00
11.	1	FRONT FENDER/RH	659.00	659.00
12.	1	FRONT FENDER INNER SHIELD/RH	185.00	185.00
13.	1	FRONT GRILLE	750.00	750.00
14.	1	FRONT HEADLAMP/RH	4,515.00	4,515.00
15.	1	FRONT HEADLAMP LOWER BRACKET/RH	45.00	45.00
16.	1	FRONT HEADLAMP CONTROL UNIT/RH	400.00	400.00
17.	1	FRONT SENSOR	195.00	195.00
18.	1	FRONT SENSOR HOLDERS	15.00	15.00
19.	1	FRONT SENSOR WIRE HARNESS	300.00	300.00
20.	1	FRONT WIPER TANK	165.00	165.00
21.	1	FRONT AIR-CON PIPE (IN)	435.00	435.00
22.	1	FRONT AIR-CON PIPE (OUT)	195.00	195.00
23.	1	FRONT ABSORBER/RH	2,200.00	2,200.00
24.	1	FRONT LOWER ARM/RH	454.00	454.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

31/01/2023
 16/01/2023
 No of Reports:
 Number of Reports:

YEW BOO SPRAY PAINT CO.

10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469

Estimate : OD23/017

Date : 20/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221862A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference : LYB/SKK88J/ERGO/OD/si
 Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	FRONT KNUKLE ARM/RH		<i>Sm</i> 1,020.00 X
26.	1	FRONT BEARING HUP/RH		<i>Sm</i> 420.00 X
		Total Parts Purchased S\$:		14,688.00
		20.00% Of The Above Parts S\$:		2,937.60
		Based On Cost Plus S\$:		17,625.60
		SPECIAL NETT ITEMS :		
1.	10	FRONT FENDER INNER SHIELD CLIP/RH	<i>nu</i> 5.00	50.00 —
2.	10	RIVERTS 003 990 9497MB	<i>nu</i> 5.00	50.00 —
3.	1	GST BY SUPPLIER		661.34 ?
		Special Nett Total S\$:		761.34
		LABOUR :		
		TO TRANSFER FRONT SENSORS TO NEW BUMPER		60.00 ✓
		TO CHECK/ REPAIR/ REPLACE ON WIRE HARNESS		120.00 ?
		TO VACUM & TOP UP AIR-CON GAS		80.00 ?
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION		55.00 2ol
		TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT		120.00 ?
		TO CHECK ON COMPUTERISE ALIGNMENT	<i>nu</i>	120.00 X

CONTINUE / ...



LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
Contact : 68299199 Fax No. : 63338469

Estimate : OD23/017

Date : 20/05/2023
Vehicle Num. : SKK 88J
Make/Model : MERCEDES S450L-2017
Chassis/Eng# : WDD2221662A384160/27682430784697
Accident Date : 20/05/2023
Claim No. :
Reference : LYB/SKK88J/ERGO/OD/sl
Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK/ REPAIR/ REPLACE THE AFFECTED AIR-CON PIPE		180.00 ?
		TO VACUM & TOP UP AIR-CON GAS		120.00 ?
		LABOUR TO CHECK/ REPAIR/ REPLACE RIGHT UNDER CARRIAGE AFFECTED APRTS	na	350.00 X
		TO REPAIR PANEL BEAT, RE-STRAIGHTEN ON AFFECTED PANEL, BONNET & LABOUR TO REPLACE ABOVE PARTS		1,000.00 400d
		TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT FRT FENDER, FRT BUMPER, SENSOR & TOUCH UP ON AFFECTED BONNET ONLY		1,000.00 750d
		Labour Total S\$:		3,205.00

E. & O.E.

Total S\$: 21,591.94
=====



for LIM YEW BOO SPRAY PAINT CO.