

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details			
Registration Number	SMB1323Y		
Case Reference Number	BUS/05/23/7009		
Registration Date	3/25/2013		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	A22		
Name of Driver	Jonaydi Bin Basri		
Type of Accident	Head to Rear		
Accident Date and Time	5/6/2023 9:39 PM		
Accident Reported Date and Time	5/15/2023 2:03 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC,if any	SMB1323Y - Right front body dented SLA6133M (TP) - INSURED WITH AIG		
Prepared Date and Time	5/23/2023 11:07 AM		
Chassis Number	WMAA22ZZXD7001779		
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates Summary of Repair Estimates					
Total Labour Cost	\$795.00	\$0.00			
Total Spray Cost	\$786.00	\$0.00			
Total Spare Part Cost	\$75.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$1,656.00	\$0.00			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	3.0				
Prepared / Adjusted By	Jeong Choon Hwee				
ARC / Surveyor Sign Off Date	23/05/2023 11:11 AM				
Signature	1	×			
Remarks					

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 23/05/2023
User ID : JeongCH



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 23/05/2023
User ID : JeongCH

Part 1 - Labo	ur Works								
Job Scope	ob Scope			Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00						
			\$795.00						
Part 2 - Spra	y Painting & F	Panel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00						
Total Spray Pa	Total Spray Painting & Panel Beating			\$786.00					
Part 3 - Other	Costs - Acci	dent and Accident	Repair Related Expens	se					
			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Co	sts								
Part 4 - Spare	Parts / Mate	rial Usage		•					
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010154	Body		FLAP,FRONT:FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	
6010064	Body		BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	
Total					\$4,787.30		\$75.00		
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

Total