

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005211/UQP3Q2**Date:** 19/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00019092203

Claimant Vehicle No : SMP4635D **Insured Vehicle No :** CB4737K

Date of Loss: 14/05/2023 Nature of Claim: TP Claim No: SNM23D203470/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP4635D**

Make & Model: AUDI A4, 1.4 (A) Engine No: CVN017624

Reg. Date: 23/12/2016 (Man. Year: 2016) Chassis No: WAUZZZF45HA026818

Colour: Red Odometer: 76830 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 245/35Z R19

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,791.05	4,069.80	8,721.25	68.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,080.00	2,380.00	68.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,251.05	5,149.80	11,101.25	68.31
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	16,251.05	4,100.00	12,151.05	74.77

INSPECTION

Date of Assignment: 23/05/2023

Date Inspected: 23/05/2023 Inspected At: 130 BEDOK RESERVOIR ROAD,
#08-1339,EUNOS SPRING
SINGAPORE 470130
Repairer:Zoom Autowerks Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	AUDI A4 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP4635D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,334.00 FL	*- FL
2	1		*FRONT HEADLAMP	Scratched / Cracked	2,585.00 FL	*2,585.00 FL
3	1		*FRONT HEADLAMP NOZZLE COVER	Not Necessary	68.00 FL	*- FL
4	1		*FRONT HEADLAMP NOZZLE	Not Necessary	225.00 FL	*- FL
5	1		*FRONT BUMPER	Deep Cut / Torn	1,973.00 FL	*1,581.00 FL
6	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
7	1		*FRONT BUMPER INNER SPONGE	Not Necessary	175.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	677.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER (O/S)	Cracked	78.00 FL	*78.00 FL
10	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	185.00 FL	*- FL
11	1		*FRONT FENDER (RH)	Repair	1,085.00 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD	Not Necessary	175.00 FL	*- FL
13	1		*FRONT WHEEL HUB	Not Necessary	215.00 FL	*- FL
14	1		*FRONT WHEEL BEARING	Not Necessary	105.00 FL	*- FL
15	1		*FRONT SHOCK ABSORBER	Not Necessary	560.00 FL	*- FL
16	1		*FRONT KNUCKLE ARM	Not Necessary	760.00 FL	*- FL
17	1		*FRONT LOWER ARM	Not Necessary	419.00 FL	*- FL
18	1		*FRONT TOP ARM	Not Necessary	475.00 FL	*- FL
19	1		*FRONT CONTROL ARM	Not Necessary	425.00 FL	*- FL
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
21	1		*FRONT TIRE	Not Necessary	550.00 FS	*- FS
22	1		*FRONT WHEEL RIM	Repair	1,200.00 FS	*- FS
					Sub Total (\$\$)	13,369.00 4,284.00
					- List Item Discount on L Items 5.00/5.00% (\$\$)	577.95 214.20
					Total Parts (\$\$)	12,791.05 4,069.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE DAMAGED LAMPS & CHECK UP WIRING	New	80.00	20.00
2	TO REMOVE & REFIT FRONT UNDERCARRIAGE	New	450.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
4	TO APPLY UNDERCOATING	New	150.00	0.00
5	PANEL BEATING	New	1,400.00	400.00
6	TO RE-SPRAY THE AFFECTED AREAS	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,460.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >