

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CTI, 23005211/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 4635D

at Workshop m/s Zoom

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$ 68k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 434109

Veh No: SMP 4635D Yr Regn: 23/12/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Audi A4 c.c. 1395

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 76830 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WANTZF45HA026818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35ZR19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/05/23 D.O.I. 23/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/6/23 L/S \$ 4100 : inform Elin (red \$ 1251.05, 75%)

Date/Time, File Pass to?

☐ : Preli. Report

13/6 Marcus

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Report Format : MEP-TP

Lump Sum / L.B.I. (\$) 4100)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 14TH MAY 2023

OWNER : ZHANG WENLE

REG. NO. : SMP 4635 D

MAKE/MODEL : AUDI A4

16th May 2023

not Authorised
all
2/5 \$4100/
23/5/23
Take photo after repair
4 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(\$S)
<u>LIST ITEMS</u>		
1	Front Bonnet <i>11</i>	\$ 1,334.00 X
1	Front Headlamp <i>SCR/CRA</i>	\$ 2,585.00 ✓
1	Front Headlamp Nozzle Cover <i>11</i>	\$ 68.00 X
1	Front Headlamp Nozzle <i>11</i>	\$ 225.00 X
1	Front Bumper <i>Deep cut / Torn</i>	\$ <i>1581</i> 1,973.00 —
1	Front Bumper Clip (1Set) <i>all</i>	\$ 40.00 —
1	Front Bumper Inner Sponge <i>11</i>	\$ 175.00 X
1	Front Bumper Reinforcement <i>11</i>	\$ 677.00 X
1	Front Bumper Side Retainer <i>2/5 CRA</i>	\$ 78.00 —
1	Front Bumper Side Grille <i>11</i>	\$ 185.00 X
1	Front Fender (RH) <i>2</i>	\$ 1,085.00 X
1	Front Fender Inner Shield <i>11</i>	\$ 175.00 X
1	Front Wheel Hub <i>11</i>	\$ 215.00 X
1	Front Wheel Bearing <i>11</i>	\$ 105.00 X
1	Front Shock Absorber <i>11</i>	\$ 560.00 X
1	Front Knuckle Arm <i>11</i>	\$ 760.00 X
1	Front Lower Arm <i>11</i>	\$ 419.00 X
1	Front Top Arm <i>11</i>	\$ 475.00 X
1	Front Control Arm <i>11</i>	\$ 425.00 X
		\$ 11,559.00
LESS 5%		\$ 577.95
		\$ 10,981.05
<u>SPECIAL NETT ITEMS</u>		
1	Front Fender Inner Shield Clip (1Set) <i>11</i>	\$ 60.00 X
1	Front Tire <i>11</i>	\$ 550.00 X
1	Front Wheel Rim <i>2</i>	\$ 1,200.00 X

S/N

LABOUR CHARGES

- | | |
|---|--|
| 1 | To remove, replace damaged lamps & check up wiring |
| 2 | To remove & refit front undercarriage |
| 3 | To conduct wheel alignment |
| 4 | To apply undercoating |
| 5 | Panel Beating |
| 6 | To re-spray the affected areas |

\$ 1,810.00

\$	80.00	20
\$	11	450.00 X
\$		180.00 60
\$	11	150.00 X
\$		1,400.00 400
\$		1,200.00 600

\$ 3,460.00

\$ 16,251.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4284
52
P- 4069.80
L- 1080
5149.80
206
4119.