

REF: HLA/ 23005213/Kg

## ASSIGNMENT

Veh No: SLU 7035B Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Audi A4 C.C. 1395

Colour M. Green A/C: Insured / Std / NI / NA

Sp. Reading 139448 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZF48JA027049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STP A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: 225/50R17

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI

TOYO/YOKO on

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 21/5/23

**Survey held at**

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

No 2nd parts for this make & model

☐: Prell. Report

**Final Report**

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$

: Interview (S

Tech Invs (\$

Weekend (\$

### Report Format :

**Lump Sum / I.B.I: (\$**

1974

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2023)

Parts: 143 AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/SLU7035B/23/05/2023 11:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                             | %Disc | %Depr | Amount |                |
|-----|-----|----------|-----------------------------------------|-------|-------|--------|----------------|
| 1   | 1   |          | *FRONT BUMPER FASCIA                    | CM    | 0.00  | 0.00   | *900.00 F ✓    |
| 2   | 1   |          | *FRONT LH BUMPER INNER PARTS            |       | 0.00  | 0.00   | *82.00 F 7     |
| 3   | 1   |          | *FRONT LH BUMPER INNER PARTS CLIP (SET) |       | 0.00  | 0.00   | *36.00 F 7     |
| 4   | 1   |          | *FRONT LH BUMPER NOZZLE COVER           |       | 0.00  | 0.00   | *72.00 F 7     |
| 5   | 1   |          | *FRONT LH BUMPER NOZZLE COVER SPRING    | RM    | 0.00  | 0.00   | *28.00 F 7     |
| 6   | 1   |          | *FRONT LH BUMPER NOZZLE                 | RM    | 0.00  | 0.00   | *190.00 F 7    |
| 7   | 1   |          | *FRONT LH BUMPER NOZZLE BRACKET         |       | 0.00  | 0.00   | *25.00 F 7     |
| 8   | 1   |          | *FRONT LH BUMPER NOZZLE HOSE            |       | 0.00  | 0.00   | *155.00 F 7    |
| 9   | 1   |          | *FRONT LH BUMPER GRILLE                 |       | 0.00  | 0.00   | *130.00 F 7    |
| 10  | 1   |          | *FRONT BUMPER UNDER COVER               | RM    | 0.00  | 0.00   | *195.00 F 7    |
| 11  | 1   |          | *FRONT BUMPER REINFORCEMENT             | R     | 0.00  | 0.00   | *450.00 F X    |
| 12  | 1   |          | *FRONT LH BUMPER REINFORCEMENT SUPPORT  | RM    | 0.00  | 0.00   | *195.00 F X    |
| 13  | 1   |          | *FRONT BUMPER SPONGE                    |       | 0.00  | 0.00   | *130.00 F 7    |
| 14  | 1   |          | *FRONT SUPPORT TOP COVER                |       | 0.00  | 0.00   | *125.00 F 7    |
| 15  | 1   |          | *FRONT LH FENDER                        | RM    | 0.00  | 0.00   | *420.00 F 7    |
| 16  | 1   |          | *FRONT LH FENDER LOWER BRACKET          |       | 0.00  | 0.00   | *36.00 F 7     |
| 17  | 1   |          | *FRONT LH FENDER INNER SUPPORT          |       | 0.00  | 0.00   | *90.00 F 7     |
| 18  | 1   |          | *FRONT LH FENDER INNER LOWER BRACKET    |       | 0.00  | 0.00   | *55.00 F 7     |
| 19  | 1   |          | *FRONT LH FENDER FRONT BRACKET          |       | 0.00  | 0.00   | *72.00 F 7     |
| 20  | 1   |          | *FRONT LH FENDER INNER SHIELD           |       | 0.00  | 0.00   | *185.00 F 7    |
| 21  | 1   |          | *FRONT LH FENDER INNER SHIELD LOWER     | DIT   | 0.00  | 0.00   | *90.00 F 7     |
| 22  | 5   |          | *FRONT LH FENDER INNER SHIELD RIVET     |       | 0.00  | 0.00   | *15.00 F 7     |
| 23  | 5   |          | *FRONT LH FENDER INNER SHIELD CLIP      | RM    | 0.00  | 0.00   | *10.00 F 7     |
| 24  | 1   |          | *LH HEADLAMP                            | RM    | 0.00  | 0.00   | *2,950.00 F 7  |
| 25  | 1   |          | *LH HEADLAMP POWER MODULE               | CM    | 0.00  | 0.00   | *370.00 F 7    |
| 26  | 1   |          | *LH HEADLAMP LED CONTROL MODULE         |       | 0.00  | 0.00   | *580.00 F 7    |
| 27  | 1   |          | *LH HEADLAMP BREATHER HOSE              |       | 0.00  | 0.00   | *66.00 F 7     |
| 28  | 1   |          | *LH HEADLAMP SEALFRAME                  |       | 0.00  | 0.00   | *82.00 F 7     |
| 29  | 1   |          | *FRONT GRILLE                           |       | 0.00  | 0.00   | *470.00 F 7    |
| 30  | 1   |          | *FRONT NO.PLATE WITH BOX                | CM    | 0.00  | 0.00   | *50.00 FS 25JN |

F=Franchise part. S=SpcNett.

Sub Total (S\$) 8,254.00  
+ Margin on L,N Items 10.00% (S\$) 820.40

Total Parts (S\$) 9,074.40

Alan's United Auto Pte Ltd/SLU7035B/23/05/2023 11:53. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No Particulars

Lab.Type

Amount

### Labour Items

|   |                                                                                            |     |            |
|---|--------------------------------------------------------------------------------------------|-----|------------|
| 1 | TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM,DIAGNOS & RESET HEADLAMP SYSTEM            | New | 601 150.00 |
| 2 | TO PUTTY AND SPRAY REPLACED PARTS                                                          | New | 601 800.00 |
| 3 | TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS | New | 501 800.00 |

Gross Labour Cost (\$\$)

1,750.00

Alan's United Auto Pte Ltd/SLU7035B/23/05/2023 11:53. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Bld 7 Sin Ming Industrial Estate, #01-76  
Singapore 575642  
Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com; Janicechou@alanutd.com

INSURER:

HL Assurance Pte Ltd (HQ)

## PARTICULARS OF CLAIM

|                     |                          |                       |             |
|---------------------|--------------------------|-----------------------|-------------|
| Claim Type:         | OD (OWN DAMAGE)          | Ref. No:              | 023111      |
| Policy No:          | MP308804                 | Date of Loss:         | 21/05/2023  |
| Vehicle Reg. No.:   | SLU7035B                 | Driveable?            |             |
| Driver Age/Info:    | / MALE                   | Party At Fault:       | UNKNOWN     |
| TP Injury Involved? | NO                       | Third Party Involved? | YES         |
| Insured/Claimant:   | LIM KIA WEE (LIN JIAWEI) | Contact No:           | +6598009278 |
| Driver:             | LIM KIA WEE (LIN JIAWEI) |                       |             |

  

|                 |                                |                    |                   |
|-----------------|--------------------------------|--------------------|-------------------|
| Make/Model:     | AUDI A4, 1.4 TFSI S TRONIC (A) | Vehicle Reg. Date: | 07/12/2017        |
| Vehicle Colour: | GREY                           |                    |                   |
| Engine No:      | CVN044761                      | Chassis No:        | WAUZZZF46JA021049 |
| Odometer:       | 0 KM                           |                    |                   |

  

|                               |          |  |  |
|-------------------------------|----------|--|--|
| Paint Type:                   |          |  |  |
| Total Loss?                   | NO       |  |  |
| Est. Duration of Repair (day) | ~ 5 days |  |  |

*Not Notified*  
*Repair B4 paint*  
*Ex \$600*

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

## COST OF CLAIMS

|                         | Amount           |
|-------------------------|------------------|
| Parts                   | 9,074.40         |
| Miscellaneous Items     | 0.00             |
| Labour                  | 1,750.00         |
| Paintwork Labour        | 0.00             |
| Towing                  | 0.00             |
| <b>Gross Total (\$)</b> | <b>10,824.40</b> |
| <b>+ GST 8.00% (\$)</b> | <b>865.95</b>    |
| <b>Nett Amount (\$)</b> | <b>11,690.35</b> |

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System