Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: HL Assurance Pte Ltd From: LKK Auto Consultants Pte Ltd 11 Keppel Road 51 Ubi Ave 1 #01-25

#11-01 ABI Plaza Paya Ubi Industrial Park Singapore 089057 Singapore 408933

Attn: 14 Jul 2023 Romeo Jonnalyn Alaan Date:

Preliminary Advice

Vehicle No : SLU7035B **Accident Date** : 21/05/2023 Policy No. Make : AUDI A4 : MP308804 Assignment Date : 23/05/2023 Excess : S\$600.00 Date of Inspection : 24/05/2023 Est. Duration of Repair : 5

Inspection At : ALAN'S UNITED AUTO PTE LTD (HQ)

BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76

SINGAPORE 575642

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,978.40 (Estimate \$10,824.40 + Supplementary \$154.00)
-----------------------------	------	---

Revised Amount :S\$ 7.511.10 Check Items (Estimated) :S\$ 0.00 Total :S\$ 7,511.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
New for Old Value	.5

Pre-Accident Value :S\$ 93,000.00 COE / PARF Rebate :S\$ 45,482.00

Salvage Value :S\$

Margin for Repair :S\$ 47,518.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kin	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: KINDLY APPROVE ON SUPPLEMENTARY. (X)