

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

TO	: NTUC (FBT7990S)	DATE	: 22-May-23
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX400E	P -	\$ 1024.20
		S -	\$ 230.00
		L -	\$ 990.00
VEHICLE DETAILS		TOTAL :	\$ 2244.20
VEHICLE NO.	: SLR4849E	L/S -20% :	\$ 448.84
MODEL / MAKE	: MIT ATTRAGE	SUB TOTAL :	\$ 1795.36
CHASSIS NO.	: MMBSTA13AHH004314		
ACCIDENT DETAIL			
DATE	: 21-May-23		
TIME	: 14:20HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	REAR BOOT LID LOGO EMBLEM	1	\$ 41.00	\$ net 41.00
2	REAR BOOT LID ATTRAGE EMBLEM	1	\$ 35.00	\$ net 35.00
3	REAR BOOT LID LOCK	1	\$ 206.00	\$ net 206.00
4	REAR BOOT LID WEATHER STRIP	1	\$ 148.00	\$ net 148.00
5	REAR BUMPER	1	\$ 708.00	\$ net 708.00
6	REAR BUMPER SIDE RETAINER LH / RH	2	\$ 26.00	\$ X 52.00
7	REAR BUMPER REFLECTOR RH	1	\$ 20.00	\$ X 20.00
8	REAR END PANEL	1	\$ 402.00	\$? 402.00
9	REAR END PANEL INNER TOP GARNISH	1	\$ 62.00	\$? 62.00
TOTAL PRICE				\$ 1,674.00
LESS -10%				\$ (167.40)
SUB TOTAL PRICE				\$ 1,506.60

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ 30 net 60.00
2	REAR BUMPER REVERSE SENSOR SET	1	\$ 280.00	\$ 200 net 280.00
3	REAR END PANEL INNER TOP GARNISH CLIPS SET	1	\$ 50.00	\$ X 50.00
4	REAR END PANEL SEALANT	1	\$ 80.00	\$ X 80.00

TOTAL

\$ 470.00

230.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 800.00	500 400	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 600.00	400	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 120.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 150.00	30	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 250.00	60.	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 100.00	X	

TOTAL

\$ 2,170.00

990.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 1,976.60
TOTAL LABOUR COST	:	\$ 2,170.00
TOTAL REPAIR COST	:	\$ 4,146.60

APPROVED DETAILS

NO. OF REPAIR DAYS : 3-4 DAYS

REPAIR UNDER : PART BY PART OR LUMPSUM

DATE / TIME OF SURVEY : 23/5/23

SURVEYED BY / FROM : Taufik LKH.

CONTACT NUMBER : 97495747 / 62563561

EMAIL ADDRESS : taufik@lkhauto.com.

taufik@LKHauto.com