



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

INCOME INSURANCE LTD  
75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557  
ATTN: YO YO TIAN TIAN

Ref: CS/INC23005220/Tnp3m4  
Date: 06/06/2023  
Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SML 7627D	<b>Veh. Inspected</b>	SHD 1681L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1223872-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	23/05/2023

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	KIA NIRO PLUS HYBRID	<b>c.c</b>	1580
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2023
<b>Chassis No.</b>	KNAA381CVPT011456	<b>Colour</b>	SILVER
<b>Odometer</b>	42234 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/55R17	NEXEN	6 mm
<b>L/H Front Tyre</b>	215/55R17	NEXEN	6 mm
<b>R/H Rear Tyre</b>	215/55R17	NEXEN	6 mm
<b>L/H Rear Tyre</b>	215/55R17	NEXEN	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	19/05/2023	<b>Inspect Date / Time</b>	24/05/2023 ( 02:30 PM )
<b>Survey held at</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**