



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD

INCOME CENTRESINGAPORE 189557

ATTN: LIM SERENE

Ref: CS/INC23005227/Tqp3e2

Date: 02/08/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SMX 2602U            | Veh. Inspected | SBS 6516R  |
| Policy No.   |                      | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1222801-002       | Excess (\$)    | 0.00       |
| Assign From  | HAZALYSA BIN IBRAHIM | Assign Date    | 23/05/2023 |

### 2. Vehicle Particulars & Condition

|              |                      |              |          |
|--------------|----------------------|--------------|----------|
| Make & Model | MERCEDES BENZ CITARO | c.c          | 6374     |
| Engine No.   | HIDDEN               | Year of Reg. | 2014     |
| Chassis No.  | WEB62808323127661    | Colour       | GREEN    |
| Odometer     | 572244 KM            | Steering     | IN ORDER |
| Brakes       | IN ORDER             | Modification | NIL      |
| General      | GOOD                 |              |          |

### 3. Conditions of Tyres

|                | Size             | Make    | Balance |
|----------------|------------------|---------|---------|
| R/H Front Tyre | 275/70 R22.5     | FIRENZA | 8 mm    |
| L/H Front Tyre | 275/70 R22.5     | FIRENZA | 8 mm    |
| R/H Rear Tyre  | 275/70 R22.5 (D) | FIRENZA | 8/8 mm  |
| L/H Rear Tyre  | 275/70 R22.5 (D) | FIRENZA | 8/8 mm  |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |                               |                     |                         |
|----------------|-------------------------------|---------------------|-------------------------|
| Accident Date  | 13/05/2023                    | Inspect Date / Time | 24/05/2023 ( 02:15 PM ) |
| Survey held at | 2 LOYANG WAY SINGAPORE 508776 |                     |                         |
| Repairer       | BOXFRESH PTE LTD              |                     |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days