

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005229/TQP3Q2**Date:** 27/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00227872200		
Claimant Vehicle No :	SMU8816X	Insured Vehicle No :	SLX5577B		
Date of Loss:	19/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203612/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8816X		Engine No:	CZDA51371
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)		Chassis No:	WVGZZZ1TZKW072374
Reg. Date:	01/09/2020 (Man. Year: 2019)		Odometer:	29719 km
Colour:	Beige			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,402.78	1,707.08	1,695.70	49.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,400.00	3,280.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,082.78	4,107.08	4,975.70	54.78
+ GST 8.00/8.00% (S\$)	726.62	328.57	398.05	54.78
Nett Amount (S\$)	9,809.40	4,435.65	5,373.75	54.78

INSPECTION

Date of Assignment:	23/05/2023		
Date Inspected:	25/05/2023	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2023)
Parts: M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMU8816X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*VW SIGN BLACK /BRIGHT CHRO	Not Necessary	122.53 FS	*- FS	
2	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -TOURAN	Not Necessary	96.80 FS	*- FS	
3	1		*COVER FOR BUMPER PRIMED	Deformed	1,307.91 FS	*1,307.91 FS	
4	1		*SPOILER SATIN BLACK	Deformed	399.17 FS	*399.17 FS	
5	1		*BUMPER REINFORCEMENT	Not Necessary	766.55 FS	*- FS	
6	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	80.40 FS	*- FS	
7	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	58.20 FS	*- FS	
8	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	58.20 FS	*- FS	
9	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	56.51 FS	*- FS	
10	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	56.51 FS	*- FS	
11	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS	
					Total Parts (S\$)	3,402.78	1,707.08

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	2,400.00	800.00
			Gross Labour Cost (\$\$)	5,680.00
				2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >