

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

25/5/2023 @ 4:15 p.m.  
(LKK)

Page 1/2

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
CINDY  
LOH YOKE FUN  
7 PINE GROVE  
#11-04  
SINGAPORE 597592

Document no.  
Document date 23-05-2023  
Customer no. 5211001170  
Customer GST-ID 200208384E  
Dealer 30001  
Job order number 2023013720/ 1  
Job order date 22-05-2023  
Service Advisor SHU SHI TANG

License plate SMU8816X	Model code 5T13NZC1	First registration 01-09-2020	VIN WVGZZZ1TZKW072374	Model Touran Comfortline EQP 1.4 TSI 110kW DSG	Mileage 22,927
---------------------------	------------------------	----------------------------------	--------------------------	--	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6 ✓	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6 ✓	480.00	518.40
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs. nn x	122.53	#6	122.53	132.33
5TA853687 ZZZ	Inscription Bright Chrome NAME PLATE - TOURAN	1	pcs. nn x	96.80	#6	96.80	104.54
5TA807417 GRU	Cover For Bumper Primed	1	pcs. de	1,307.91	#6	1,307.91	1,412.54
5TA807568A 9B9	Spoiler Satin Black	1	pcs. de	399.17	#6	399.17	431.10
5TA807305	Bumper REINFORCEMENT	1	pcs. xnn ?	766.55	#6	766.55	827.87
5TA807863	Attachment Strip	1	pcs. xnn ?	80.40	#6	80.40	86.83
5TA807453	BUMPER CTR BRACKET						
5TA807453	Guide Piece	1	pcs. xnn x	58.20	#6	58.20	62.86
5TA807454	LHR BUMPER BRACKET ( UPPER )						
5TA807454	Guide Piece	1	pcs. xnn x	58.20	#6	58.20	62.86
5TA807393	RHR BUMPER BRACKET ( UPPER )						
5TA807393	Guide Piece	1	pcs. xnn x	56.51	#6	56.51	61.03
5TA807394	LHR BUMPER BRACKET ( SIDE )						
5TA807394	Guide Piece	1	pcs. xnn x	56.51	#6	56.51	61.03
	RHR BUMPER BRACKET ( SIDE )						
	LABOUR	3	pcs. 840	840.00	#6	2,520.00	2,721.60
	SPRAY PAINT	3	pcs. 800	800.00	#6	2,400.00	2,592.00
	REVERSE SENSOR	1	pcs. xnn ?	400.00	#6	400.00	432.00
	CHINA TAIPING DIRECT DOA: 19/5/2023 TP VEH: SLX5577B SURVEY BY:						
				\$4107.08			
				3 days #			

Quotation valid till 29-05-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,322.78	8%	726.62	9,082.78	9,809.40
<b>Total</b>	<b>760.00</b>	<b>8,322.78</b>		<b>726.62</b>	<b>9,082.78</b>	<b>9,809.40</b>

Customer

Tanjim 97495749  
WP 25/5/23 @ 4:30pm  
PP Resurvey before paint  
3 days  
Tanjim @ lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Service Advisor

Acknowledged by Repairer

Signature:

Date: