

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0489/2023/EQ
DATE : 23-May-23
WIP : 21841

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TEO JIA YUN (ZHANG JIAYUN)
ADDRESS : BLK 721 BEDOK RESERVOIR ROAD
#04-4622
SINGAPORE 470721
TELEPHONE : HP +65 97243909
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230018346
VEHICLE NO : **SKU 908 R**
MODEL CODE : AUDI Q3 SPORTBACK 1.5 TFS
MODEL YEAR : 27/2/2023
ENGINE NO : DFY 359883
CHASSIS NO : WAUZZZF32P1016334
MILEAGE : 2,891
DATE IN : 22-May-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-May-23
PLACE OF ACCIDENT : BEDOK RESERVOIR ROAD, FILTER ROAD TO BEDOK NORTH ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 908 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	?
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00	X
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	X
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	500
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,000.00	1500 550 x 2 = 1100 Wheel Arch x 2 = 400 1500
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,672.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 908 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,679.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 458.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LH ?	1	\$ 70.00	?	
4	FRONT BUMPER TRIM ?	1	\$ 421.00	?	
5	FRONT BUMPER GRILLE - CENTER ?	1	\$ 256.00	?	
6	FRONT PARKING AID SENSOR SUPPORT - LH / RH ?	2	\$ 62.00	?	
7	FRONT BUMPER LOWER GRILLE COVER ?	1	\$ 61.00	?	
8	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 224.00	?	
9	FRONT BUMPER SPOILER <i>crushed</i>	1	\$ 900.00	✓	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 181.00	+	
11	FRONT BUMPER TRIM - LH <i>new</i>	1	\$ 193.00	+	
12	FRONT PARKING AID SENSOR SUPPORT - LH ?	1	\$ 31.00	?	
13	RADIATOR GRILLE <i>crushed</i>	1	\$ 2,262.00	✓	
14	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 288.00	+	
15	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 242.00	+	
16	RADIATOR GRILLE BRACKET <i>new</i>	1	\$ 51.00	+	
17	RADIATOR GRILLE SECURING PLATE <i>new</i>	1	\$ 39.00	+	
18	RADIATOR GRILLE COVER <i>new</i>	1	\$ 288.00	+	
19	FRONT "360" CAMERA <i>new</i>	1	\$ 1,326.00	+	
20	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 543.00	+	
SUB TOTAL SPARE PARTS			\$ 9,575.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 908 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	+
22	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 643.00	+
23	HORN HIGH TONE - LH <i>new</i>	1	\$ 157.00	+
24	HORN BRACKET - LH <i>new</i>	1	\$ 26.00	+
25	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 121.00	?
26	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 1,030.00	?
27	FRONT BUMPER GUIDE SECTION - LH ?	1	\$ 46.00	?
28	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 145.00	+
29	CAUTION SIGN STICKER <i>new</i>	1	\$ 17.00	+
30	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	+
31	FRONT FENDER - LH <i>Rep New</i>	1	\$ 1,530.00	+
32	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 69.00	+
33	FRONT FENDER BRACE - LH <i>new</i>	1	\$ 104.00	+
34	FRONT FENDER BRACKET - LH <i>new</i>	1	\$ 55.00	+
35	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 281.00	+
36	FRONT FENDER GUARD PLATE COVER - LH <i>new</i>	1	\$ 19.00	+
37	HEADLIGHT MOUNTING - LH / RH ?	2	\$ 280.00	?
38	HEADLIGHT - LH ?	1	\$ 6,305.00	?
39	LIFT CYLINDER - LH <i>new</i>	1	\$ 244.00	+
40	LIFT CYLINDER HOSE <i>new</i>	1	\$ 96.00	+
SUB TOTAL SPARE PARTS			11,188.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 908 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	LOCK CARRIER <i>Free</i>	1	\$	1,497.00	+
42	READY-MIX COOLANT	6	\$	326.00	+
43	RADIATOR LOUVRE <i>Free</i>	1	\$	473.00	+
44	RADIATOR SERVMOTOR	1	\$	205.00	+
45	RADIATOR AIR GUIDE - UPPER <i>Free</i>	1	\$	61.00	+
46	RADIATOR AIR GUIDE - LOWER <i>Free</i>	1	\$	53.00	+
47	RADIATOR AIR GUIDE - LH / RH <i>Free</i>	2	\$	94.00	+
48	WIRE SET <i>Free</i>	1	\$	415.00	+
49	FRONT WHEEL COVER - LH / RH <i>Free</i>	2	\$	1,200.00	✓
50	FRONT NUMBER PLATE <i>Free</i>	S/N	\$	60.00	✓
51	SUNDRIES		\$	500.00	✓
TOTAL SPARE PARTS		:	\$	25,647.00	
TOTAL LABOUR CHARGES		:	\$	12,672.00	
GRAND TOTAL		:	\$	38,319.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *23/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALIAN WU
CLAIMS CONSULTANT