

Estimate

MOVA AUTOMOTIVE PTE LTD

08 BUKIT MERAH, LANE 3 #01-04 SINGAPORE 159722,
Singapore, Singapore, Singapore - 159722.
VAT: 198904033G
Contact: +65 62723892
Email: NITHA@MOVA.COM.SG

Company Name: INDIA INTERNATIONAL INSURANCE
Address: 64 Cecil Street, #04-02 IOB Building
City: Singapore
Region: Central Singapore
Postal Code: 049711
Co.Reg.No: 198703792K

Proforma Invoice No:

Date: May 22 2023

Ticket No: MAP-J000029

Vehicle No: SKZ9300H

Policy No: 000

Claim No: 0

Customer: Lee Haohong

Vehicle: HONDA JAZZ MT 2016

Kilometer: 110130

Color: WHITE

Fuel: PETROL

PH: +65 93673582

Email:

#	Part Name	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	RADIATOR GRILLE <i>con</i>	Part	8	1.00	314.20	251.36	62.84	251.36	271.47
2	HEADLAMP ASSY RH & LH <i>X</i>	Part	8	2.00	1,470.70	1,176.56	588.28	2,353.12	2,541.37
3	HEADLAMP LOWER BRACKET RH & LH <i>X</i>	Part	8	2.00	43.10	34.48	17.24	68.96	74.48
4	FRONT BUMPER <i>de</i>	Part	8	1.00	538.10	430.48	107.62	430.48	464.92
5	FRONT BUMPER REINFORCEMENT <i>X</i>	Part	8	1.00	238.70	190.96	47.74	190.96	206.24
6	FRONT BUMPER RETAINER RH & LH <i>de</i>	Part	8	2.00	19.50	15.60	7.80	31.20	33.70
7	FRONT BUMPER LOWER GRILLE - CENTER <i>?</i>	Part	8	1.00	49.80	39.84	9.96	39.84	43.03
8	FRONT BUMPER CLIPS <i>de</i>	Part	8	10.00	5.90	4.72	11.80	47.20	50.98
9	FRONT NUMBER PLATE <i>con 5/1035</i>	Part	8	1.00	40.00	40.00	0.00	40.00	43.20
10	TAILGATE <i>bt</i>	Part	8	1.00	851.40	681.12	170.28	681.12	735.61
11	TAILGATE GLASS MOULDING <i>de</i>	Part	8	1.00	117.60	94.08	23.52	94.08	101.61
12	TAILGATE GLASS SEALANT <i>de</i>	Part	8	1.00	40.00	32.00	8.00	32.00	34.56
13	TAILGATE CHROME MOULDING <i>X</i>	Part	8	1.00	228.40	182.72	45.68	182.72	197.34
14	TAIL GATE EMBLEM - JAZZ <i>de</i>	Part	8	1.00	28.00	22.40	5.60	22.40	24.19
15	TAILGATE LOCK <i>cut</i>	Part	8	1.00	157.60	126.08	31.52	126.08	136.17
16	TAILGATE WEATHERSTRIP <i>de</i>	Part	8	1.00	92.30	73.84	18.46	73.84	79.75
17	REAR END PANEL <i>bt</i>	Part	8	1.00	350.40	280.32	70.08	280.32	302.95
18	REAR END PANEL TOP COVER <i>de</i>	Part	8	1.00	65.40	52.32	13.08	52.32	56.51
19	REAR BUMPER <i>de</i>	Part	8	1.00	554.20	443.36	110.84	443.36	478.83
20	REAR BUMPER BRACKET RH & LH <i>de</i>	Part	8	2.00	25.10	20.08	10.04	40.16	43.37
21	REAR BUMPER RETAINER RH & LH <i>de</i>	Part	8	2.00	25.10	20.08	10.04	40.16	43.37
22	REAR BUMPER CLIPS <i>de</i>	Part	8	10.00	5.90	4.72	11.80	47.20	50.98
23	REVERSE SENSOR <i>?</i>	Part	8	1.00	200.00	200.00	0.00	200.00	216.00
								Taxable Value	5,768.88
								GST Total	461.55
								Discount Total	1,382.22
								Grand Total	6,230.43

#	Service	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
24	TO CUT / WELD REAR END PANEL, KNOCK & STRAIGHTEN REAR BODY MEMBER, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	Labour	8	-	1,000.00	1,000.00	0.00	1,000.00	<i>800</i> 1,080.00
25	SPRAY PAINT TAILGATE, REAR END PANEL, REAR BODYMEMBER, REAR BUMPER, SUPPORT PANEL	Labour	8	-	1,200.00	1,200.00	0.00	1,200.00	<i>800</i> 1,296.00
26	REMOVE & REPLACE A/C CONDENSER & PIPE, HOSE, RECHARGE A/C GAS	Labour	8	-	120.00	120.00	0.00	120.00	<i>X</i> 129.60

Service	Description	GST (%)	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
REMOVE & REPLACE TAILGATE GLASS & CHECK WATER LEAKAGE	Labour	8	-	120.00	120.00	0.00	120.00	120 129.60
REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	Labour	8	-	60.00	60.00	0.00	60.00	60 64.80
29 REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING	Labour	8	-	60.00	60.00	0.00	60.00	40 64.80
30 RUST PROOF AFFECTED AREAS / TAILGATE INNER TRIM -CHECK	Labour	8	-	50.00	50.00	0.00	50.00	40 54.00
						Taxable Value		2,610.00
						GST Total		208.80
						Discount Total		0.00
						Grand Total		2,818.80

		Parts Total	5,768.88
		Labour Total	2,610.00
		GST Total	670.35
		Grand Total	9,049.23
		Balance	9,049.23

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
 Hf 96010068
 7 days
 4/5
 30/05/23 @ 1500
 Repair after
 refund