

Strides Automotive Services Pte Ltd (Co.Reg.No:199004280Z)

60 Woodlands Industrial Park E4

Singapore 757705

Tel: 68662628 Fax: 63687421 Email: feiyuan@smrt.com.sg;wongkokwah@smrt.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
INDIA INSURANCE INTERNATIONAL SINGAPORE

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TAX/05/23/2061
Policy No:		Date of Loss:	21/05/2023
Vehicle Reg. No.:	SHB5424Y	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	30/11/2017
Vehicle Colour:	MAROON	Gen Condition:	GOOD
Engine No:	2ZRS109448	Chassis No:	JTDKKB3FU203575570
Odometer:	538168 KM		
Paint Type:			
List Item Discount:	25.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	ACCIDENT INVOLVING SHB5424Y AND GBM2673C AT TOA PAYOH LOR 2 TOWARDS TOA PAYOH AVE 2		
Remarks:	PLEASE CALL CHAN MUN SAN OR TAY BOON CHEW @ 6866-2623 TO ARRANGE FOR SURVEY. LOCATION TO SURVEY : 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE, 757705		
Present Location:	STRIDES AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	10,158.89
Miscellaneous Items	1,696.00
Labour	1,014.00
Paintwork Labour	1,636.00

Towing

0.00

Nett Amount (S\$)

14,504.89

This claim is handled by: CHAN MUN SAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2023)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB5424Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SEALANT SIKAFLEX	0	0.00	*37.00 FS
2	1		*SPARE TYRE PANEL , PAN, REAR FLOOR	25.00	0.00	*630.30 FL
3	1		*END PANEL SUB-ASSY, BODY LOWER BACK	25.00	0.00	*707.10 FL
4	1		*STICKER DECAL 6555 8888	0	0.00	*21.60 FS
5	1		*STRIDES LOGO	0	0.00	*7.80 FS
6	1		*EMBLEM SUB-ASSY REAR	25.00	0.00	*77.40 FL
7	1		*TAIL GATE LOCK COVER , BACK DOOR	25.00	0.00	*32.70 FL
8	1		*TAIL GATE LOCK ASSY, BACK DOOR	10.00	0.00	*505.50 FN
9	3		*SEALANT W/SCREEN (3PCS)	0	0.00	*111.00 FS
10	1		*TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	25.00	0.00	*821.20 FL
11	1		*TAIL GATE GLASS SUB-ASSY, BACK DOOR	25.00	0.00	*1,795.00 FL
12	1		*NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	25.00	0.00	*59.10 FL
13	1		*NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	25.00	0.00	*59.10 FL
14	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	25.00	0.00	*992.30 FL
15	1		*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	25.00	0.00	*31.10 FL
16	1		*TAIL GATE WEATHERSTRIP, BACK DOOR	25.00	0.00	*402.50 FL
17	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	25.00	0.00	*1,238.40 FL
18	1		*COVER, REAR FLOOR UNDER CENTER	25.00	0.00	*249.10 FL
19	1		*COVER, REAR FLOOR UNDER , LH	25.00	0.00	*261.60 FL
20	1		*COVER, REAR FLOOR UNDER , RH	25.00	0.00	*189.20 FL
21	1		*LENS & BODY ASSY , RR BUMPER , LH	10.00	0.00	*544.40 FN
22	1		*LENS & BODY ASSY , RR BUMPER , RH	10.00	0.00	*544.40 FN
23	1		*LENS & BODY, REAR COMBINATION LAMP , LH	10.00	0.00	*489.00 FN
24	1		*LENS & BODY, REAR COMBINATION LAMP , RH	10.00	0.00	*489.00 FN
25	1		*REAR BUMPER GROMMET SCREW	25.00	0.00	*2.20 FL
26	1		*ANTENNA, ELECTRICAL KEY	25.00	0.00	*78.00 FL

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
27	1		*SENSOR REVERSE	0	0.00	*180.00 FS
28	1		*COVER, GUARD RR BUMPER LOWER	25.00	0.00	*16.70 FL
29	1		*FILLER, RR BUMPER , LH	25.00	0.00	*168.60 FL
30	1		*FILLER, RR BUMPER , RH	25.00	0.00	*168.60 FL
31	1		*GUARD, RR BUMPER, LOWER	25.00	0.00	*623.50 FL
32	10		*CLIPS PIECE, FRT & RR BUMPER	25.00	0.00	*48.00 FL
33	1		*SEAL, RR BUMPER , LH	25.00	0.00	*95.50 FL
34	1		*SEAL, RR BUMPER , RH	25.00	0.00	*95.50 FL
35	1		*RETAINER, RR BUMPER, LH	25.00	0.00	*127.40 FL
36	1		*RETAINER, RR BUMPER, RH	25.00	0.00	*127.40 FL
37	1		*STOPPER, RR BUMPER, RH & LH	25.00	0.00	*4.80 FL
38	1		*SEAL, RR BUMPER ARM, RH & LH	25.00	0.00	*12.30 FL
39	1		*PAD, RR BUMPER, CTR	25.00	0.00	*2.50 FL
40	2		*PAD, RR BUMPER, RH & LH , 3	25.00	0.00	*8.60 FL
41	2		*PAD, RR BUMPER, RH & LH , 2	25.00	0.00	*8.60 FL
42	2		*PAD, RR BUMPER, RH & LH , 1	25.00	0.00	*8.60 FL
43	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*360.10 FL
44	1		*COVER, RR BUMPER ASSY	25.00	0.00	*478.90 FL

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (S\$)	12,911.60
- List Item Discount on L Items (S\$)	2,495.48
- Nett Item Discount on N Items (S\$)	257.23
Total Parts (S\$)	10,158.89

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00
2	1	TO CHECK & RESET SYSTEM FUNCTION	350.00
3	1	TO CHECK WIRING AND SYSTEM FUNCTION	120.00
4	1	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	475.00
5	1	TO REMOVE AND REFIX REAR WINDSCREEN	240.00
6	1	TO REPLACE SUNDRY PARTS	100.00
7	1	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00
8	1	TO TRANSFER REAR TAILGATE MECHANISM	120.00
9	1	TO WASH AND VACUUM	60.00
10	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			1,696.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY REAR SPARE TYRE PANEL	New	220.00
2	TO RESPRAY BUMPER BEAM	New	220.00
3	TO RESPRAY REAR BUMPER	New	378.00
4	TO RESPRAY REAR PANEL	New	220.00
5	TO RESPRAY TAIL GATE	New	378.00
6	TO RESPRAY TAILGATE OUTSIDE GARNISH	New	220.00
Labour Items			
7	TO REPAIR REAR PORTION	New	1,014.00
Gross Labour Cost (S\$)			2,650.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >