

ASS. REC. BY:

REF:

*IV / 230052371ky*

*C*

*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s *SMRT*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *034* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *S11B54244* Yr Regn: *111 CF*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toy Prius* c.c. *1798*

Colour: *N. Brown* A/C: Insured / Std / NI / NA

Sp. Reading: *538168* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JTDKCB3FU203575570*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt or

Brake: *Inorder* / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: *195/65R15*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *PoRun*

Front

R/Bal. *9* mm

L/Bal. *9* mm

D.O.A. *21/5/23*

Rear

R/Bal. *9* mm

L/Bal. *9* mm

D.O.I. *25/5/2023*

Survey held at \_\_\_\_\_

Des. of Damages: Frit / *Rear* O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*14/6 11 Rng @ 3000 Corbu*

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: \_\_\_\_\_

1)

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:  : Site Insp (\$ )

: Interview (\$ )

: Tech Invs (\$ )

: Weekend (\$ )

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

SMRT Accident Vehicle Repair Estimates

SMRT Auton  
60 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera  
User ID

Section A - Accident Details

Registration Number	SHB5424Y
Case Reference Number	TAX/05/23/2061
Registration Date	30/11/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	FARALI KHAN BIN BABU KHAN
Type of Accident	Head to Rear
Accident Date and Time	21/5/23 11:55 AM
Accident Reported Date and Time	22/5/23 10:07 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118472
Special Instruction to ARC,if any	TP/REAR PORTION
Prepared Date and Time	22/5/23 10:21 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,636.00	\$0.00
Total Spare Part Cost	\$8,127.15	\$0.00
Total Other Cost	\$1,685.00	\$0.00
<b>TOTAL COST</b>	<b>\$12,462.15</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$12,450.00</b>	<b>\$0.00</b>
Number of Repair Days	7.0	03 days + 1
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	22/05/2023 10:39 AM	
Signature		Kenneth
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**SMRT Accident Vehicle Repair Estimates**

SMRT Auton  
60 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera  
User ID

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR REAR PORTION	\$1,014.00 <i>400</i>	
<b>Total Labour</b>	<b>\$1,014.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00 <i>nn X</i>	
TO RESPRAY BUMPER BEAM	\$220.00 <i>720</i>	
TO RESPRAY REAR BUMPER	\$378.00 <i>200</i>	
TO RESPRAY REAR PANEL	\$220.00 <i>nn X</i>	
TO RESPRAY TAIL GATE	\$378.00 <i>nn X</i>	
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00 <i>150</i>	
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,636.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO WASH AND VACUUM	\$60.00 <i>nn X</i>	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20</i>	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>nn X</i>	
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00 <i>nn X</i>	
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00 <i>nn X</i>	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>50</i>	
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00 <i>nn X</i>	
TO REPLACE SUNDRY PARTS	\$100.00 <i>nn X</i>	
TO CHECK & RESET SYSTEM FUNCTION	\$350.00 <i>5 X</i>	
<b>Total Other Costs</b>	<b>\$1,685.00</b>	

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace <i>nn</i>	<i>X</i>
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace <i>SL</i>	<i>X</i>
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace <i>nn</i>	<i>—</i>
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace <i>Bu</i>	<i>✓</i>
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace <i>Bu</i>	<i>✓</i>
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace <i>Mc</i>	<i>—</i>
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace <i>Mc</i>	<i>—</i>
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace <i>Mc</i>	<i>—</i>
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace <i>Mc</i>	<i>—</i>
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace <i>Del/Di</i>	<i>✓</i>
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace <i>nn</i>	<i>X</i>
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace <i>nn</i>	<i>X</i>
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace <i>nn</i>	<i>X</i>
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace <i>nn</i>	<i>X</i>

**SMRT Accident Vehicle Repair Estimates**

SMRT Auton  
60 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera  
User ID

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace <i>Sh</i>	X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	10.00	\$440.10	Replace <i>Sh</i>	X
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$489.00	10.00	\$440.10	Replace <i>Sh</i>	X
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	10.00	\$489.96	Replace <i>Sh</i>	X
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	10.00	\$489.96	Replace <i>Sh</i>	X
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace <i>Sh</i>	X
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace <i>Sh</i>	X
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace <i>mi's</i>	✓
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	X
		6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$402.50	25.00	\$301.88	Replace <i>Sh</i>	X
		5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1.00	\$31.10	25.00	\$23.33	Replace <i>nn</i>	X
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace <i>cm</i>	✓
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace <i>nn</i>	✓
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace <i>nn</i>	✓
		6935047050	TAIL GATE LOCK ASSY, BACK DOOR	1.00	\$505.50	10.00	\$454.95	Replace <i>ll</i>	X
		6932147010	TAIL GATE LOCK COVER, BACK DOOR	1.00	\$32.70	25.00	\$24.53	Replace <i>Sh</i>	X
		5831147130	SPARE TYRE PANEL, PAN, REAR FLOOR	1.00	\$630.30	25.00	\$472.72	Replace	X
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace <i>ll</i>	X
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace <i>mc</i>	✓
		6810547291	TAIL GATE GLASS SUB-ASSY, BACK DOOR	1.00	\$1,795.00	25.00	\$1,346.25	Replace <i>Sh</i>	X
		6480147031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1.00	\$821.20	25.00	\$615.90	Replace <i>Sh</i>	X
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace <i>mc</i>	✓
		5246147010	PAD, RR BUMPER, CTR	1.00	\$2.50	25.00	\$1.88	Replace <i>mc</i>	✓
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace <i>Sh</i>	X
		5259968030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace <i>m</i>	X
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace <i>Sh</i>	X
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace <i>Sh</i>	X
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace <i>Sh</i>	X
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace <i>Sh</i>	X
			SEALANT W/SCREEN (3PCS)	3.00	\$37.00	0.00	\$111.00	Replace <i>nn</i>	X
<b>Total</b>					<b>\$12,781.50</b>		<b>\$10,158.94</b>		