

Section A - Accident Details

Registration Number	SHB5424Y
Case Reference Number	TAX/05/23/2061
Registration Date	30/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	FARALI KHAN BIN BABU KHAN
Type of Accident	Head to Rear
Accident Date and Time	21/May/2023 11:55 AM
Accident Reported Date and Time	22/May/2023 10:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118472
Special Instruction to ARC, if any	TP/REAR PORTION
Prepared Date and Time	22/May/2023 10:21 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,814.00	\$520.00
Total Spray Cost	\$2,554.00	\$590.00
Total Spare Part Cost	\$8,378.67	\$1,819.02
Total Other Cost	\$1,696.00	\$81.00
TOTAL COST	\$14,442.67	\$3,010.02
Lump Sum Total	\$14,450.00	\$3,000.00 (L/S)
Number of Repair Days	10.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Ill
ARC / Surveyor Sign Off Date	29/05/2023 8:49 AM	27/05/2023 10:58 AM
Signature		<i>Kenneth</i>
Remarks	INITIAL = 7 DAYS WITH SUPPLEMENTARY = 3 DAYS TOTAL = 10 DAYS	(EXTENDED OF 1 DAY) LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2306-0057	Invoice Number	
Quotation Date	12.06.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
TO REPAIR REAR TAILGATE	\$200.00	\$0.00
TO REPLACE REAR END PANEL	\$200.00	\$120.00
TO REPAIR PANEL SIDE ROOF LH	\$200.00	\$0.00
TO REPAIR PANEL SIDE ROOF RH	\$200.00	\$0.00
Total Labour	\$1,814.00	\$520.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$120.00
TO RESPRAY PANEL SIDE ROOF LH	\$180.00	\$0.00
TO RESPRAY PANEL SIDE ROOF RH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$220.00	\$120.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$220.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$150.00
Total Spray Painting & Panel Beating	\$2,554.00	\$590.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
OD/TP case (Insurer)	\$11.00	\$11.00
Total Other Costs	\$1,696.00	\$81.00

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2023

User ID : PohSuan

			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√ nec
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Check	X
		58311471 30	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$630.30	0.00	\$0.00	Replace	Not Given	X } nn
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X }
Total					\$12,781.50		\$2,261.29			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.53	Replace	Replace	√
		67881470 50	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$402.50	0.00	\$0.00	Replace	Not Given	X nn
Total					419.20		12.53			

	2,273.82	
	-20%	
	1819.06	L/S \$3,000/-
+	520.00	
+	671.00	
	<u>3,010.06</u>	