

ESTIMATE FOR SNJ104R

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 64754
Reg No/Reg Date SNJ104R / 16/12/2022
Date In/Mileage / 0
Chassis No W1K2231602A1659786
Engine No 25693030553090
Make/Model MB/S 450 SEDAN LONG
Colour/Trim 025 595 Nautic Blue/ 048 801 Nappa Black

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|-------------------|
| WA000001 | Credit | 05/05/2023/ 10:31 | CH | 371 / Go Chee Han |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : SP2003907937 // 20-1-2023

DRIVE IN/EXCESS : 28-4-2023 // TBA

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

A BPILAB

CHECK DAMPING FOR RADAR BEAM ON REAR BUMPER (AFTER QUICK TEST)

M REAR BUMPER

| | | | |
|------|---------|-------|---------|
| 1.00 | 2182.24 | 00.00 | 2182.24 |
| 1.00 | 116.36 | 00.00 | 116.36 |
| 1.00 | 116.36 | 00.00 | 116.36 |
| 1.00 | 775.93 | 00.00 | 775.93 |
| 1.00 | 221.12 | 00.00 | 221.12 |
| 1.00 | 150.19 | 00.00 | 150.19 |
| 1.00 | 833.67 | 00.00 | 833.67 |

M LH/REAR BUMPER TRIM STRIP

M RH/REAR BUMPER TRIM STRIP

M REAR BUMPER LOWER PART

M LH/TAIL PIPE TRIM STRIP

M LH/REAR BUMPER MOUNTING RAIL

M LH/OUTER REAR LAMP COMBINATION

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

| | |
|---------------|----------|
| Nett | 7,635.87 |
| 8% GST on | 7635.87 |
| Total Payable | 8,246.74 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg