



簡福星嘍王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCV22A00017500	Date of Loss:	20/05/2023
Vehicle Reg. No.:	GBL5923S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CREATE LOGIC PTE LTD		
Make/Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Vehicle Reg. Date:	01/11/2021
Vehicle Colour:	WHITE		
Engine No:	1KDB089145	Chassis No:	KDY318049489
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	3,533.20
Miscellaneous Items	50.00
Labour	1,230.00
Paintwork Labour	720.00
Towing	0.00
Calculated Gross Total (S\$)	5,533.20
- Excess (S\$)	600.00
(S\$)	4,933.20
+ GST 8.00% (S\$)	394.66
Nett Amount (S\$)	5,327.86

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 May 2023)
 Parts: N/A TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/GBL5923S/24/05/2023 13:16
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN RUBBER <i>an</i>	0.00	0.00	*95.00 F
2	1		*FRONT WIPER PANEL <i>an</i>	0.00	0.00	*125.00 F
3	1		*FRONT PANEL <i>an</i>	0.00	0.00	*380.00 F
4	1		*FRONT PANEL DYNA EMBLEM <i>an</i>	0.00	0.00	*20.00 F
5	1		*FRONT GRILLE <i>an</i>	0.00	0.00	*180.00 F
6	1		*FRONT GRILLE EMBLEM <i>an</i>	0.00	0.00	*28.00 F
7	8		*FRONT GRILLE CLIP <i>an</i>	0.00	0.00	*24.00 F
8	1		*FRONT HEADLAMP RH <i>an</i>	0.00	0.00	*300.00 F
9	1		*FRONT HEADLAMP LH <i>an</i>	0.00	0.00	*300.00 F
10	1		*FRONT BUMPER <i>an</i>	0.00	0.00	*230.00 F
11	1		*FRONT BUMPER BRACKET RH <i>an</i>	0.00	0.00	*95.00 F
12	1		*FRONT BUMPER BRACKET LH <i>an</i>	0.00	0.00	*95.00 F
13	1		*AIR CON BLOWER <i>?</i>	0.00	0.00	*890.00 F
14	1		*HEATER UNOT <i>?</i>	0.00	0.00	*450.00 F

F=Franchise part.

Sub Total (S\$)	3,212.00
+ Margin on L,N Items 10.00% (S\$)	321.20
Total Parts (S\$)	3,533.20

Kan Fook Sing Motor Workshop/GBL5923S/24/05/2023 13:16. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT NUMBER PLATE <i>cm</i>	35	50.00
			Sub Total (S\$)	50.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	SPRAYPAINTING CHAREGS	New	600	720.00
---	-----------------------	-----	-----	-------------------

Labour Items

2	TO CHECK WIRING SYSTEM	New	30	50.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New		120.00
4	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	120?	180.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	200	880.00

Gross Labour Cost (S\$) 1,950.00

Kan Fook Sing Motor Workshop/GBL5923S/24/05/2023 13:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Repair
 Hp 90010068
 6 days
 4/5
 26/05/23 @ 1420
 EXCESS: TBA
 Repair
 Repair after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	616G
Vehicle No.:	GBL59235
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	1KDB089145
Chassis No.:	KDY2318049489
Maximum Power Output:	-
Open Market Value:	\$32,654.00
Original Registration Date:	01 Nov 2021
First Registration Date:	01 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$1,633.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Oct 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,589.00
COE Rebate Amount:	\$35,880.00
Total Rebate Amount:	\$35,880.00

The information contained herein is correct as at 28 May 2023


OK

Toyota Dyna 150 3.0M

\$105,800 Instalment \$1,403/mth

♡ Shortlist

📄 Loan Calculator



Overview Financial Photo Research

Depreciation	ⓘ \$13,650 / year
Reg. Date	26-Feb-2021 (7yrs 8mths 28days COE left)
Lifespan	ⓘ 25-Feb-2041
Manufactured	ⓘ 2021
Mileage	26,000 km (11.6k / year)
Transmission	Manual
Engine Cap	2,982 cc
Curb Weight	ⓘ 2,020 kg
Fuel Type	Diesel
COE	ⓘ \$36,138
OMV	ⓘ \$29,446
ARF	ⓘ \$1,473
Dereg Value	ⓘ \$28,019 as of today
No. of Owners	ⓘ 1
Type of Veh	<u>Truck</u>