



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE CIVIL DEFENCE FORCE (MHA05)		Ref:	CS/SCD23005256/Tqp3e2
91 UBI AVE 4 SINGAPORE 408827		Date:	07/06/2023
ATTN: FARZANAH BEGAM		Code:	SCD
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	XE 5178C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	FARZANAH BEGAM	Assign Date	22/05/2023
2. Vehicle Particulars & Condition			
Make & Model	SCANIA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	YS2P4X200K2159029	Colour	RED
Odometer	10538 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	315/70 R22.5	PIRELLI	8 mm
L/H Front Tyre	315/70 R22.5	PIRELLI	8 mm
R/H Rear Tyre	315/70 R22.5 (D)	PIRELLI	8/8 mm
L/H Rear Tyre	315/70 R22.5 (D)	PIRELLI	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	24/05/2023
Survey held at	FIRE STATION PAYA LEBAR FIRE STATION 91, UBI AVE 4, SP 408827		
5a. Remarks			



Registration No. XE 5178C

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
A	LABOUR DESCRIPTION					
1	To dismantle entire LH side compartment for damage repairs					12
2	To dismantle locker 1 slider track for damage repairs					8
3	To dismantleno 1 roller shutter for damage repairs					4
4	To cut & weld locker 1 pillar					24
5	To cut & weld locker 1 front body bottom frame					32
6	To cut & weld angle support for bottom frame					20
7	To cut & weld damage LH rear mudguard step					20
8	To replace damage swing down support brackets					20
9	To replace damage shelf support base & support brackets					12
10	To realign & panel beat rear LH wheel arch					12
11	To putty & spray paint damage rear LH wheel arch					8
12	To replace damage no 1 roller shutter					4
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				176

Vehicle Inspected By

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 5178C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

