

Registration No. XE 5178C

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
A	<b>LABOUR DESCRIPTION</b>					
1	To dismantle entire LH side compartment for damage repairs					12
2	To dismantle locker 1 slider track for damage repairs					8
3	To dismantleno 1 roller shutter for damage repairs					4
4	To cut & weld locker 1 pillar					24
5	To cut & weld locker 1 front body bottom frame					32
6	To cut & weld angle support for bottom frame					20
7	To cut & weld damage LH rear mudguard step					20
8	To replace damage swing down support brackets					20
9	To replace damage shelf support base & support brackets					12
10	To realign & panel beat rear LH wheel arch					12
11	To putty & spray paint damage rear LH wheel arch					8
12	To replace damage no 1 roller shutter					4
<b>COSTING</b>		<b>TOTAL PARTS COST</b>				
		<b>TOTAL MAN-HOUR</b>				<b>176</b>









