



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/05/2023
TP Veh Reg No: GBJ9316D

Not Authorised
11 Pay @ 4100h
Penalty After Paint
4 days

Estimate No: ES2300060
Date: 23 May 2023
Policy No:
Veh Reg No: SND3622Z
Make/Model: B.M.W. 640I GRAN COUPE M SPORT LED SR NAV HUD
Chassis No: WBA6A02040DZ11829
Engine No: 03328558N55B30A
Reg. Date: 30/09/2013

Estimate Repair Cost to Vehicle No :SND3622Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Spare Parts				
1 FRONT DOOR - RH <i>1680-20</i>	2,200.00	1 PC	<i>Bz</i> 2,200.00	✓
2 FRONT DOOR CHECKER - RH	185.50	1 PC	<i>Sm</i> 185.50	X
3 FRONT DOOR GLASS OUTER MOULDING - RH	280.00	1 PC	<i>Sm</i> 280.00	X
4 FRONT DOOR HANDLE - RH	220.00	1 PC	<i>Red</i> 220.00	✓
5 FRONT DOOR INNER TRIMBOARD - RH	1,065.50	1 PC	<i>mhc at</i> 1,065.50	✓
6 FRONT DOOR LOCK - RH	400.00	1 PC	<i>Th</i> 400.00	✓
7 FRONT DOOR REGULATOR GEAR - RH	480.00	1 PC	<i>Doit</i> 480.00	✓
8 FRONT DOOR REGULATOR GEAR MOTOR - RH	420.00	1 PC	<i>Th</i> 420.00	✓
9 FRONT DOOR RIVET	96.00	1 PC	<i>Sm</i> 96.00	✓
10 FRONT DOOR WEATHERSTRIP - RH <i>97-60W</i>	195.20	1 PC	<i>Sm</i> 195.20	<i>508W</i>
11 REAR DOOR - RH	2,800.00	1 PC	<i>R</i> 2,800.00	X
12 REAR DOOR CHECKER - RH	185.50	1 PC	<i>Sm</i> 185.50	X
13 REAR DOOR INNER TRIMBOARD - RH	1,065.50	1 PC	<i>Sm</i> 1,065.50	X
14 REAR DOOR OUTER MOULDING - RH	280.00	1 PC	<i>Sm</i> 280.00	X
15 REAR DOOR REGULATOR GEAR - RH	420.00	1 PC	<i>Sm</i> 420.00	X
16 REAR DOOR REGULATOR GEAR MOTOR - RH	380.00	1 PC	<i>Sm</i> 380.00	X
17 REAR DOOR RIVET - RH	96.00	1 SET	<i>Sm</i> 96.00	X
18 REAR DOOR WEATHERSTRIP - RH <i>59</i>	195.20	1 PC	<i>Sm</i> 195.20	X
			10,964.40	10,964.40
Labour				
19 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	<i>400</i>
20 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	<i>500</i>
21 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	<i>300</i>
22 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	<i>200</i>
23 COMPUTER DIAGNOSTIC	400.00	1 JOB	<i>nm</i> 400.00	X
			3,750.00	3,750.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/05/2023
TP Veh Reg No: GBJ9316D

Estimate No: **ES2300060**
Date: 23 May 2023
Policy No:
Veh Reg No: **SND3622Z**
Make/Model: B.M.W. 640I GRAN
COUPE M SPORT LED
SR NAV HUD
Chassis No: WBA6A02040DZ11829
Engine No: 03328558N55B30A
Reg. Date: 30/09/2013

Estimate Repair Cost to Vehicle No :SND3622Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 14,714.40
			Add GST @ 8%	1,177.15
			Total Amount Payable	S\$ 15,891.55

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND EIGHT HUNDRED NINETY ONE AND CENTS FIFTY FIVE ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE