

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8700A

DATE: 22.05.23

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 20.05.23

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40 Rv
1	REAR BUMPER CENTRE MOULDING			\$451.25 de
1	REAR BUMPER BEAM			\$394.80 ?
10	REAR BUMPER CLIPS			\$22.00 de
1	BOOTLID EMBLEM - IONIQ			\$31.30 de
1	BOOTLID EMBLEM - HYBRID			\$24.30 de
1	BOOTLID EMBLEM - H			\$28.00 nt
1	REAR FOG ALMP			\$210.50 nt
1	ANTENNA ASSY - SMARTK			\$40.50 ?
1	REAR BUMPER CENTRE UNDER COVER			\$255.00 x
1	REAR BUMPER TOW COVER			\$98.80 x
1	BOOTLID COVER			\$2,549.70 bb
1	BOOTLID GLASS LOWER MOULDING			\$145.20 mm
	REAR WINDSCREEN GLASS - SMALL			\$584.90 he
1	BOOTID GLASS UPPER MOULDING			\$186.30 nt
	SUB TOTAL			\$5,481.95
	LESS 20%			\$1,096.39
	DISCOUNTED TOTAL			\$4,385.56
	REVERSE SENSOR			\$180.00 NET
	REAR BOOTLID COMFORT LOGO			\$30.00 NET
	REAR BOOTLID TEL.NOS LOGO			\$30.00 NET
	REAR BOOTLID APPS LOGO			\$40.00 NET
	REAR WINDSCREEN SEALANT			\$46.00 NET
	RERA BUMPER MAT			\$50.00 NET
	REAR NUMBER PLATE			\$55.00 NET
	SUB TOTAL			\$431.00
	DISCOUNTED TOTAL			
	Labour Charge			
	PANEL BEATING		525	\$1,100.00
	SPRAY PAINT		500	\$600.00
	REMOVE / REFIX REVERSE SENSOR		30	\$50.00
	CHECK WIRING		30	\$50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS		✓	\$120.00
	TOTAL LABOUR			\$1,920.00
	ESTIMATE TOTAL			\$6,736.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Taufik 97495749

wp 22/5/23 Rv

L5 Resurvey after repair

Taufik @tkhendoca

03 days

air quantity
ice company

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 22.05.2023 11:21

Page : 1

Repair TP(CLSO)1

JOB CARD

Sales Order: 5897601

JC NO 305555319

COMFORT TRANSPORTATION PTE LTD

NO. 7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

JUNT CARD NO.

REGN NO.:

SHC8700A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN
21.05.2023 04:00

YR OF MANU.

26.06.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164467

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 20.05.2023

ATURE: 3P.20.5.23

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHC8700A

JU CHINA

Vehicle No.:

SHC8700A

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard