



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23005285/Kqp3e2	
			Date: 31/05/2023	
			Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 5553H	Veh. Inspected	SCU 685C
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/23/2060	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	23/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JM6BP2SAAK1103413	Colour	WHITE
	Odometer	60739 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	215/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/45 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	20/05/2023	Inspection Date	25/05/2023
	Survey held at	REVOL CARZ GARAGE PTE LTD BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$100,000.00			