

ASS. REC. BY:

REF:

INC / 230052861KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 5769C

Yr Regn:

12, 19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Pro

C.C.

1788

Colour:

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

221470

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4703088784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun 195/65R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/5/23

D.O.I.

24/5/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S/F

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S - RS - SI

F - RS

Others

Report Format:

Lump Sum / L.B.I.: (\$

TOTAL

TP 41

SMRT Accident Vehicle Repair Estimates

SMRT Auton
80 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

Section A - Accident Details

Registration Number	SHB5769C
Case Reference Number	TAX/05/23/2010
Registration Date	12/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	HUANG YAOKUN
Type of Accident	Side Swipe
Accident Date and Time	3/5/23 11:00 PM
Accident Reported Date and Time	4/5/23 3:07 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118331
Special Instruction to ARC, if any	TP
Prepared Date and Time	23/5/23 3:27 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$1,196.00	\$0.00
Total Spare Part Cost	\$12,461.10	\$0.00
Total Other Cost	\$976.00	\$0.00
TOTAL COST	\$15,647.10	\$0.00
Lump Sum Total	\$15,650.00	\$0.00
Number of Repair Days	8.0	4 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	23/05/2023 3:50 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00 4001	
Total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00 2001	
TO RESPRAY FRONT FENDER LH	\$378.00 2001	
TO RESPRAY APRON PANEL LH	\$220.00 ?	
TO RESPRAY REAR PANEL	\$220.00 X	
Total Spray Painting & Panel Beating	\$1,196.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00 ✓	
TO WASH AND VACUUM	\$60.00 X	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00 201	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 301	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 601	
TO REMOVE AND REFIT TYRE	\$120.00 201	
TO REMOVE AND REFIX UNDERCARRIAGE	\$300.00 ?	
TO REPLACE SUNDRY PARTS	\$100.00 X	
Total Other Costs	\$976.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52119-47960	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	HT ✓
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	HT ✓
		52128-47910	COVER, FR BUMPER LH	1.00	\$32.70	25.00	\$24.53	Replace	HT ✓
		53112-47310	GRILLE, RADIATOR	1.00	\$192.80	25.00	\$144.60	Replace	HT X
		53101-47100	GRILLE SUB-ASSY	1.00	\$457.10	25.00	\$342.83	Replace	HT X
		53111-47140	GRILLE, SUB-ASSY, 2	1.00	\$170.20	25.00	\$127.65	Replace	HT X
		75310-33050	EMBLEM ASSY FRONT	1.00	\$114.30	25.00	\$85.73	Replace	HT X
		51451-12120	COVER ASSY, ENGINE	1.00	\$261.60	25.00	\$196.20	Replace	HT ?
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	HT ✓
		52618-47130	ABSORBER, FR BUMPER LOWER	1.00	\$143.60	25.00	\$107.70	Replace	HT ?
		52611-47210	ABSORBER, FR BUMPER	1.00	\$86.60	25.00	\$64.95	Replace	HT ?
		52132-47010	REINFORCEMENT FRONT LOWER	1.00	\$265.90	25.00	\$199.42	Replace	HT X
		52021-47110	REINFORCEMENT FRONT UPPER	1.00	\$773.90	25.00	\$580.43	Replace	HT X
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	HT ✓
		81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$4,079.80	10.00	\$3,671.82	Replace	HT X
		81220-12240	LAMP ASSY, FOG, LH	1.00	\$256.50	10.00	\$230.85	Replace	HT ?
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$511.20	25.00	\$383.40	Replace	HT ?
		51444-12080	COVER, ENGINE UNDER SIDE LH	1.00	\$86.20	25.00	\$64.65	Replace	HT X

SMRT Accident Vehicle Repair Estimates

 SMRT Author
 RE Woodland
 Part Number
 Estimate To
 Accident Ref

Date Generated

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ag
		53802-47100	FENDER SUB-ASSY. FR LH	1.00	\$1,060.70	25.00	\$795.53	Replace <i>Re</i>	✓
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$58.10	100.00	\$0.00	Replace <i>Re</i>	✓
		53875-47060	LINER, FR FENDER, LH	1.00	\$127.80	25.00	\$95.85	Replace <i>CMH</i>	✓
		53857-20710	RETAINER, FR WHEEL RH	1.00	\$3.50	25.00	\$2.63	Replace <i>Di</i>	✓
		53828-47070	PROTECTOR, FR FENDER LH	1.00	\$101.80	25.00	\$76.35	Replace	?
		53852-47041	PAQ, FR WHEEL, LH	1.00	\$85.20	25.00	\$63.90	Replace	?
		53702-47101	APRON SUB-ASSY, FRONT FENDER, LH	1.00	\$1,060.90	25.00	\$795.68	Replace <i>Re</i>	X
		42811-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace <i>Di</i>	✓
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace <i>Re</i>	X
		43212-47040	KNICKLE, STEERING LH	1.00	\$717.50	25.00	\$538.13	Replace	?
		45047-49195	END SET, TIE ROD, LH	1.00	\$202.30	25.00	\$151.73	Replace	?
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	1.00	\$803.20	25.00	\$602.40	Replace	?
		43330-19115	JOINT ASSY, LOWER BALL RH & LH	1.00	\$284.50	25.00	\$213.38	Replace	?
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	1.00	\$511.40	25.00	\$383.55	Replace	?
		48620-47040	LINK ASSY, FRONT STABILIZER, RH & LH	1.00	\$256.40	25.00	\$192.30	Replace	?
		48811-12500	BAR, STABILIZER, FR	1.00	\$382.60	25.00	\$286.95	Replace	?
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace <i>Re</i>	✓
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	?
Total					\$13,686.94		\$15,863.33		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Gr
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/05/2023 16:44 (SGT)
Reported by	Actual Driver
Date of Accident	03/05/2023 23:00 (SGT)
Exact Location of Accident	Central Blvd, Singapore
Additional Location Information	CENTRAL BOULEVARD TOWARDS BAYFRONT AVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB5769C

INSURED POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1X0000369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-23100854MFSH

DRIVER


Name of Driver	HUANG YAOKUN
NRIC No	SX0006121
Date Of Birth	04/02/1984
Occupation	Outdoor

Vehicle Registration Number	SMR238TY
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Extent Of Damage	-
Details of property damaged in accident	-
Number Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	HUANG YAOKUN
Gender	Male
Age	-
Address	-
Address Complement	-
Postcode	-
Approximate Age Years Old	-
Injuries Sustained	-
Vehicle in which person was in?	SHB5769C
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	Yes



Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

X *Y. Low*

4 MAY 2023

Lee 4.5.2023