



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 1967X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	40.00
1	LH TAKE UP GRILLE TRIM (PDC BASIS/X (SN)	NOT NECESSARY	83.10	-
10	EXPANDING RIVET BLACK (SN) (ADDITIONAL)	NECESSARY	14.00	14.00
			247.10	54.00
	<u>LABOUR</u>			
	TO REMOVE AND MAKE GOOD FRONT BUMPER.		1,700.00	850.00
	TO RESPRAY FRONT BUMPER.		1,038.00	986.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING.		177.00	168.00
			3,092.00	2,172.00
	GRAND TOTAL		3,339.10	2,226.00
	RECOMMENDED COST OF REPAIRS			2,226.00

Report Ref No. CS/FCI23005295/Rqp3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.