



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23005299/Unp3m4 Date: 09/06/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 830E	Veh. Inspected	SFD 8822A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2302071/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	24/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 8 SP (A)	c.c	2261
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JM6LY1033F0301280	Colour	WHITE
	Odometer	117512 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R16	DUNLOP	6 mm
	L/H Front Tyre	215/65 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/65 R16	TOURADOR	6 mm
	L/H Rear Tyre	215/65 R16	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/05/2023	Inspection Date	25/05/2023
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	