

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SFD8822A

Model: MAZDA 8 5-DOOR

Not Allowed

4/5 7000

5 days

25/5/23

- LKK Auto Consultants hence notify the Repairs of the following:
- To rectify before the repair work
- To repair damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification is allowed
- Supplementary item(s) must be received
- is subject to final approval from Insurance Company

Acknowledged by Repairs

Signature:

Date:

QTY	List items	Price S
1	TAIL GATE <i>Body 700</i>	1562.80 1938.35 ✓
2	TAIL GATE BADGE-MAZDA 8 <i>nee</i>	60.00 82.00 ✓
3	TAIL GATE LOGO <i>nee</i>	85.00 117.10 ✓
4	TAIL GATE WEATHERSTRIP <i>11</i>	281.30 X
5	TAIL GATE SUCTION LOCK <i>11</i>	1285.60 X
6	TAIL GATE SUCTION LOCK ECU <i>11</i>	1417.50 X
7	TAIL GATE INNER TRIM BOARD <i>cut</i>	678.30 ✓
8	TAIL GATE INNER TRIM BOARD CLIP <i>nee</i>	40 89.60 ✓
9	TAIL GATE CENTRE GARNISH <i>dis/torn</i>	620.40 1087.20 ✓
10	TAIL GATE LAMP L/R @\$689.20/PCE <i>n/s scd</i>	485.20 1378.40 1pc
11	TAIL GATE WIPER MOTOR <i>11</i>	1124.00 X
12	TAIL GATE WIDSCREEN <i>shorted</i>	1021.30 1818.00 ✓
13	TAIL GATE OUTER SPOILER <i>cut</i>	1050 1244.00 ✓
14	REAR BUMPER <i>nee</i>	1172.55 ✓
15	REAR BUMPER CLIP <i>nee</i>	40 86.00 ✓
16	REAR BUMPER SIDE RETAINER L/R @87.20/PCE <i>11</i>	174.40 X
17	REAR BUMPER SIDE HOLDER L/R @102.00/PCE <i>11</i>	204.00 X
18	REAR BUMPER SIDE REFLECTOR L/R @\$122.30/PCE <i>n/s scd o/s n</i>	244.60 1pc 60
19	REAR BUMPER REINFORCEMENT <i>n</i>	722.00 X
20	REAR BUMPER INNER FOAM <i>n/s</i>	188.00 X
21	TAIL LAMP L/R @\$874.60/PCE <i>n/s scd o/s n</i>	752.00 1749.20 1pc
22	REAR END PANEL <i>n</i>	612.00 X
23	REAR END PANEL GARNISH <i>11</i>	213.50 X
24	REAR FENDER INNER TRIM BOARD L/R @\$897.30/PCE <i>n/s cut 665</i>	1794.60 1pc
25	REAR TAIL GATE SUCTION ABSORBER ECU <i>11</i>	1308.60 X

TOTAL	21010.80
LESS 10%	2101.08
TOTAL	18909.72

Special Nett Items

1	REAR WINDSCREEN GLASS SEALANT <i>nee</i>	100.00 40
2	REAR BUMPER SENSOR <i>McKutson</i>	280.00 200
3	REAR END PANEL SEALANT <i>11</i>	100.00 X
4	REAR WINDSCREEN GLASS SOLARFILM <i>nee</i>	300.00 150
TOTAL		\$780.00

LABOUR CHARGES

1	PANEL BEATING	1600.00 500
2	SPRAY PAINTING CHARGES	1200.00 1000
3	INSTALL REAR BUMPER SENSOR	80.00 50
4	REPLACE REAR WINDSCREEN	160.00 120
5	TO REMOVE & REFIT REAR FITTINGS AND ATTACHMENT	150.00 80
6	ANTI RUST TREATMENT	280.00 30
7	TO CHECK WIRING FOR PROPER FUNCTION	150.00 20
TOTAL		3620.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

8292.55
202
\$23,309.72
6634.04