

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS / SMO23005299/4ap3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFD 8822A

at Workshop m/s End Success

of _____

Insured: GSH 830E

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 40k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

736f
Vehicle: IN / OUT

Date: _____ Person Contacted: 17A824003

Veh No: SFD 8822A Yr Regn: 23/12/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Mazda 8 sp c.c. 2261

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 117512 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6LY1033F0301280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R16

R: Touedor

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/05/23 D.O.I. 25/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/6/23</u>	<u>501 yrs 7mth RPH 15997</u>
	<u>L/S \$ 7000 inboard AH hurt (Red. \$ 16309.72, 70%)</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	736F
Vehicle Details	
Vehicle No.:	SFD8822A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 May 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA8 5-DOOR WAGON 2.3L SP. 5EAT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	L310560733
Chassis No.:	JM6LY1033F0301280
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$21,998.00
Original Registration Date:	23 Dec 2014
First Registration Date:	23 Dec 2014
Transfer Count:	1
Actual ARF Paid:	\$22,798.00 11 399
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2024
PARF Rebate Amount:	\$12,538.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$72,890.00
COE Rebate Amount:	\$11,465.00
Total Rebate Amount:	\$24,003.00

The information contained herein is correct as at 25 May 2023

OK

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SFD8822A

Model: MAZDA 8 5-DOOR

not allowed

4/54 7000

5 days

25/5/23

LKK Auto Consultants hence not the Repainer of the following:
 • To rectify before/after spray painting
 • To display damaged parts, etc. in a roomy
 • Parts prices are subject to confirm 1st
 • Third party survey is on a "Without Prejudice" basis
 • Illegal modification(s) is allowed
 • Supplementary item(s) must be re-approved
 • Is subject to final approval from Insurance Co., etc.

Acknowledged by Repainer

Signature:

Date:

QTY	List items	Price S
1	TAIL GATE <i>Body 700</i>	1562.80 1938.35 ✓
2	TAIL GATE BADGE-MAZDA 8 <i>nee</i>	60.00 82.00 ✓
3	TAIL GATE LOGO <i>nee</i>	85.00 117.10 ✓
4	TAIL GATE WEATHERSTRIP <i>11</i>	281.30 X
5	TAIL GATE SUCTION LOCK <i>11</i>	1285.60 X
6	TAIL GATE SUCTION LOCK ECU <i>11</i>	1417.50 X
7	TAIL GATE INNER TRIM BOARD <i>cut</i>	678.30 ✓
8	TAIL GATE INNER TRIM BOARD CLIP <i>nee</i>	40 89.60 ✓
9	TAIL GATE CENTRE GARNISH <i>dis/ton</i>	620.40 1087.20 ✓
10	TAIL GATE LAMP L/R @\$689.20/PCE <i>n/s sc</i>	485.20 1378.40 120
11	TAIL GATE WIPER MOTOR <i>11</i>	1124.00 X
12	TAIL GATE WIDSCREEN <i>shottard</i>	1021.30 1818.00 ✓
13	TAIL GATE OUTER SPOILER <i>cut</i>	1050 1244.00 ✓
14	REAR BUMPER <i>nee</i>	1172.55 ✓
15	REAR BUMPER CLIP <i>nee</i>	40 86.00 ✓
16	REAR BUMPER SIDE RETAINER L/R @87.20/PCE <i>11</i>	174.40 X
17	REAR BUMPER SIDE HOLDER L/R @102.00/PCE <i>11</i>	204.00 X
18	REAR BUMPER SIDE REFLECTOR L/R @\$122.30/PCE <i>n/s sc o/s n</i>	244.60 1460 140
19	REAR BUMPER REINFORCEMENT <i>n</i>	722.00 X
20	REAR BUMPER INNER FOAM <i>n/s</i>	188.00 X
21	TAIL LAMP L/R @ \$874.60/PCE <i>n/s sc o/s n</i>	752.00 1749.20 120
22	REAR END PANEL <i>R</i>	612.00 X
23	REAR END PANEL GARNISH <i>11</i>	213.50 X
24	REAR FENDER INNER TRIM BOARD L/R @\$897.30/PCE <i>n/s cut 665</i>	1794.60 120
25	REAR TAIL GATE SUCTION ABSORBER ECU <i>11</i>	1308.60 X

(202) TOTAL 21010.80
 LESS 10% 2101.08
 TOTAL 18909.72

Special Nett Items

1	REAR WINDSCREEN GLASS SEALANT <i>nee</i>	100.00 40
2	REAR BUMPER SENSOR <i>McHutten</i>	280.00 200
3	REAR END PANEL SEALANT <i>11</i>	100.00 X
4	REAR WINDSCREEN GLASS SOLARFILM <i>nee</i>	300.00 150
TOTAL		\$780.00

LABOUR CHARGES

1	PANEL BEATING	1600.00 500
2	SPRAY PAINTING CHARGES	1200.00 1000
3	INSTALL REAR BUMPER SENSOR	80.00 50
4	REPLACE REAR WINDSCREEN	160.00 120
5	TO REMOVE & REFIT REAR FITTINGS AND ATTACHMENT	150.00 80
6	ANTI RUST TREATMENT	280.00 30
7	TO CHECK WIRING FOR PROPER FUNCTION	150.00 20
TOTAL		3620.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

8292.55
 202 \$23,309.72

6634.04