6/16/23, 4:06 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd Our File No: CS/III23005301/RNP3M4 64 Cecil Street, #04-00 IOB Building

Date: 16/06/2023 Singapore 049711

**REFERENCE** 

Insured/Claimant: A ARAVIN KUMAR Policy No: D20MPC0003330\_02

Date of Loss: 21/05/2023 Nature of Claim: OD Claim No: MPC2023D0005876

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMM422T** 

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) R16B25510250 Engine No:

14/06/2019 (Man. Year: 2019) Chassis No: MRHFC5650KT000245 Reg. Date:

Colour: Black Odometer: 60352 km

1597 cc **Engine Capacity:** 

Market Value/New Car

S\$92,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16 Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		2,366.98		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	-600.00	1,766.98	-2,366.98	394.50
+ GST 8.00/8.00% (S\$)	0.00	141.36	-141.36	
Nett Amount (S\$)	-600.00	1,908.34	-2,508.34	418.06

**INSPECTION** 

Date of Assignment: 23/05/2023

KAH MOTOR CO SDN BERHAD Date Inspected: 24/05/2023 Inspected At: NO. 255 ALEXANDRA ROAD

SINGAPORE 159937

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: **HUEY YON** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/16/23, 4:06 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2023)

Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM422T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

6/16/23, 4:06 PM

Report was unsubmitted during this print-out.

< END OF ESTIMATES >