

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMM422T

Chassis No : MRHFC5650KT000245

Model : CIVIC 1.6 VTI YM2019

Owner's Name : A ARAVIN KUMAR

Ins Policy No :

Date of Accident : 21/5/2023

Document No. : SQT23001576 Page 1

Date : 23. May 2023

Customer No. : WI007

Svc Advisor : LEE CHEN SIN

Engine No : R16B25510250

Date | Time : 23. May 2023 2:03:23 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO:15440 POLICY/CLAIMS NO:D20MPC0003330 OWNER:A ARAVIN KUMAR ACC DATE:21/05/2023 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
33100-TEC-Q01	HEADLIGHT ASSY,R. <i>cm</i>	1	675.90	25	506.92	40.55	547.47
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE <i>X</i>	1	98.80	25	74.10	5.93	80.03
71121-TEA-T51	BASE,FR.GRILLE <i>X</i>	1	167.00	25	125.25	10.02	135.27
71125-TEA-T01	MOLDINGFR.GRILLE <i>X</i>	1	115.80	25	86.85	6.95	93.80
75700-TBA-A00	EMBLEM <i>X</i>	1	17.40	25	13.05	1.04	14.09
90301-ST0-003	NUT,PUSH 3MM <i>X</i>	2	2.10	25	3.15	0.25	3.40
71101-TEA-T50ZA	FACE,FR.BUMPER <i>de</i>	1	579.90	25	434.92	34.79	469.71
91505-TM8-003	CLIP,BUMPER <i>ne</i>	17	2.30	25	29.32	2.35	31.67
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>X</i>	1	10.40	25	7.80	0.62	8.42
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>X</i>	1	10.40	25	7.80	0.62	8.42
71140-TEA-T00	BEAMR.FR.BUMPER UPPER <i>?</i>	1	30.80	25	23.10	1.85	24.95
71180-TBA-K50	GARNISH ASSY,R.FR.BUMPER SIDE <i>cm</i>	1	75.90	25	56.92	4.55	61.47
33900-TEY-Y01	LIGHT ASSY R FR F <i>?</i>	1	288.90	25	216.67	17.33	234.00
71130-TEA-T00	BEAM COMPFR.BUMPER <i>?</i>	1	399.20	25	299.40	23.95	323.35
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP <i>?</i>	1	248.00	25	186.00	14.88	200.88
Sum Item					2071.25	165.68	2,236.93
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	8.00	108.00
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00 <i>250</i>		280.00	22.40	302.40

Printed on 23/5/2023 2:12:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMM422T
Chassis No : MRHFC5650KT000245
Model : CIVIC 1.6 VTI YM2019
Owner's Name : A ARAVIN KUMAR
Ins Policy No. :
Date of Accident : 21/5/2023

Document No. : SQT23001576 Page 2
Date : 23. May 2023
Customer No. : WI007
Svc Advisor : LEE CHEN SIN
Engine No : R16B25510250
Date | Time : 23. May 2023 2:03:23 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1500.00	650	1500.00	120.00	1620.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1300.00	520	1300.00	104.00	1404.00
Sum Labor					3180.00	254.40	3,434.40

Survey By

Date & Time

Excess

Status

Signature

Parul - Hp 90010068
28/05/23 P 1345
TBA
3 days / resy b & paint
Rever

Total Amount 5,251.25 420.08 5,671.33

Total (Inclusive of GST) 5,671.33

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 23/5/2023 2:12:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.