

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0502/2023/EQ
DATE : 25-May-23
WIP : 22272

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SLV 3420 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR HO YONG CHEH
ADDRESS : BLK 316A ANCHORVALE LINK
#09-179
SINGAPORE 541316
TELEPHONE : HP +65 81005321
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700008951-05
VEHICLE NO : **SLP 2496 M**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/5/2017
ENGINE NO : CHZ 368816
CHASSIS NO : WAUZZZ8V0H1072224
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-May-23
PLACE OF ACCIDENT : SENGKANG WEST ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 2496 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	500
3	TO RESPRAY REAR BUMPER, REAR END PANELLING AND REAR LID.	\$ 2,800.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,372.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 2496 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>Dehd</i>	1	\$ 2,455.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 213.00	+
3	REAR WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2	\$ 90.00	+
4	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 38.00	+
5	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	2	\$ 71.00	+
6	REAR BUMPER SPOILER <i>st ?</i>	1	\$ 279.00	?
7	REAR BUMPER REFLECTOR - LH / RH <i>new</i>	2	\$ 98.00	+
8	REAR BUMPER SIDE REINFORCEMENT <i>new</i>	1	\$ 680.00	+
9	REAR BUMPER BRACKET - LH / RH <i>new</i>	2	\$ 67.00	+
10	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 158.00	+
11	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 543.00	+
12	REAR PARKING AID SEAL RING <i>green</i>	4	\$ 11.00	+
13	REAR BUMPER WIRING SET	1	\$ 578.00	+
14	PACKING ADHESIVE	1	\$ 22.00	+
15	AUDI EMBLEM	1	\$ 152.00	+
16	"A3" INSCRIPTION	1	\$ 110.00	+
17	"TFSI" INSCRIPTION	1	\$ 110.00	+
18	REAR NUMBER PLATE	S/N	\$ 60.00	+
19	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 6,235.00	
TOTAL LABOUR CHARGES		:	\$ 5,372.00	
GRAND TOTAL		:	\$ 11,607.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *24/05/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT