



Section A - Accident Details

Registration Number	SHF185Z
Case Reference Number	TAX/05/23/2065
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	VETHARETINAM S/O P NARAYANAN @VEDARETNAM
Type of Accident	Side Swipe
Accident Date and Time	22/May/2023 1:34 PM
Accident Reported Date and Time	22/May/2023 3:06 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118478
Special Instruction to ARC, if any	TP/ RHS FRONT
Prepared Date and Time	22/May/2023 3:56 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$756.00	\$200.00
Total Spare Part Cost	\$9,155.16	\$2,418.71
Total Other Cost	\$380.00	\$20.00
TOTAL COST	\$11,136.16	\$2,838.71
Lump Sum Total	\$11,150.00	\$2,850.00 (L/S)
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Sompo
ARC / Surveyor Sign Off Date	26/05/2023 9:46 AM	26/05/2023 8:56 AM
Signature		
Remarks	INITIAL = 6 DAYS WITH SUPPLEMENTARY = 0 DAY TOTAL = 6 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2306-0022	Invoice Number	
Quotation Date	07.06.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$756.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$20.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53875470	LINER, FR FENDER, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given
		75374471	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$59.10	0.00	\$0.00	Replace	Not Given
		53801470	FENDER SUB-ASSY, FR , RH	0.00	\$1,060.70	0.00	\$0.00	Replace	Not Given
		81145476	UNIT , HEADLAMP , RH	0.00	\$2,852.40	0.00	\$0.00	Replace	Check
		81210470	LAMP ASSY, FOG, RH	0.00	\$1,029.90	0.00	\$0.00	Replace	Not Given
		52161160	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		53101470	GRILLE SUB-ASSY	0.00	\$374.40	0.00	\$0.00	Replace	Not Given
		53112472	GRILLE, RADIATOR	0.00	\$183.90	0.00	\$0.00	Replace	Not Given
		52618470	ABSORBER, FR BUMPER LOWER	0.00	\$143.60	0.00	\$0.00	Replace	Not Given
		52132470	REINFORCEMENT FRONT LOWER	1.00	\$265.90	100.00	\$0.00	Replace	Repair
		52102470	EXTENSION SUB-ASSY, RH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given
		52103470	EXTENSION SUB-ASSY, LH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given
		52611471	ABSORBER, FR BUMPER	0.00	\$85.90	0.00	\$0.00	Replace	Not Given
		52021471	REINFORCEMENT FRONT UPPER	0.00	\$773.90	0.00	\$0.00	Replace	Not Given
		52115470	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given

X
X
X
X
X
X
√
X
X
X
X
R
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/06/2023

User ID : PohSuan

		52119479 62	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.23	Replace	Replace	√
Total					\$7,964.30		\$456.23			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81145476 91	UNIT , HEADLAMP , RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace
Total					2,852.40		2,567.16		

	3,023.39	
	-20%	
	<hr/> 2418.71	L/S \$2,850/-
+	200.00	
+	<hr/> 220.00	
	2,838.71	