

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005309/TVP3Q2**Date:** 27/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00217742202
Claimant Vehicle No :	SKZ5488B	Insured Vehicle No :	SJW3083B
Date of Loss:	20/05/2023	Nature of Claim: TP	Claim No: SNM23D203639/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ5488B		
Make & Model:	MAZDA 5, 2.0 5DR WAGON L SP.6EAT SUNROOF (A)	Engine No:	PE10290825
Reg. Date:	27/01/2016 (Man. Year: 2015)	Chassis No:	JM6CW1071G0123037
Colour:	Grey	Odometer:	67927 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,380.08	3,158.80	1,221.28	27.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,090.00	550.00	33.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,020.08	4,248.80	1,771.28	29.42
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	6,020.08	3,400.00	2,620.08	43.52
+ GST 8.00/8.00% (S\$)	481.61	272.00	209.61	43.52
Nett Amount (S\$)	6,501.69	3,672.00	2,829.69	43.52

INSPECTION

Date of Assignment:	25/06/2023	
Date Inspected:	17/07/2023	Inspected At: Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Jul 2023)	
Parts:	N/A	MAZDA 5 2.0 5DR WAGON L SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ5488B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Cracked	1,482.00 FL	*1,482.00 FL
2	1		*FRONT BUMPER	Torn	1,108.00 FL	*1,108.00 FL
3	1		*FRONT BUMPER RETAINER RH	Deformed	39.00 FL	*39.00 FL
4	10		*FRONT BUMPER CLIPS	Necessary	47.20 FS	*30.00 FS
5	1		*FOG LAMP GARNISH RH	Not Necessary	56.00 FL	*- FL
6	1		*WASHER TANK	Deformed	125.00 FL	*125.00 FL
7	1		*FRONT FENDER RH	Bent	322.00 FL	*322.00 FL
8	1		*FRONT FENDER COWLING RH	Deformed	210.00 FL	*210.00 FL
9	10		*FRONT FENDER COWLING CLIPS	Necessary	44.80 FS	*20.00 FS
10	1		*FRONT FENDER CORNER GARNISH RH	Not Necessary	48.10 FL	*- FL
11	1		*FRONT KNUCKLE HUB RH	Not Necessary	150.00 FL	*- FL
12	1		*FRONT KNUCKLE BEARING RH	Not Necessary	159.00 FL	*- FL
13	1		*FRONT KNUCKLE ARM RH	Not Necessary	386.00 FL	*- FL
14	1		*FRONT LOWER ARM RH	Not Necessary	410.00 FL	*- FL
15	1		*FRONT SHOCK ABSORBER RH	Not Necessary	265.00 FL	*- FL
16	1		*FRT FENDER INNER PANEL RH (NPA)	Repair	0.00 FL	*- FL
17	1		*FRONT SPORT RIM RH	Cut	480.00 FS	*480.00 FS
					Sub Total (\$\$)	5,332.10 3,816.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	952.02 657.20
					Total Parts (\$\$)	4,380.08 3,158.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN FRONT FENDER INNER PANEL RH ,REMOVE & REPLACE ACCIDENT DAMAGED PARTS ,REALIGN ALL CONNECTION	New	600.00	400.00
2	SPRAY PAINT FRONT BUMPER ,FRONT FENDER INNER PANEL RH FRONT FENDER RH ,FRONT DOOR RH	New	800.00	600.00
3	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION RH	New	150.00	0.00
4	COMPUTER WHEEL ALIGNMENT	New	60.00	60.00
5	RUST PROOF AFFECTED AREAS	New	30.00	30.00
Gross Labour Cost (\$\$)			1,640.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >