

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1623005318/U203

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNC2205G

at Workshop m/s Specialists

of GBF13627

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$102k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: 1.3 / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

806C L7A558908

Veh No: SNC2205G Yr Regn: 17/012/16.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Lexus RX200T c.c. 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 185547 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ITIBAMCA 802002744

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/55-R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 23k.

Tp owner NOT agree spray rear portion only he want spray whole car because if spray rear portion only toll on have 2 tone

* NO 2nd hand parts Tp owner insist want replace new parts

Tailgate \$4080.60, Tailgate outer cover \$2464.10 1090 \$1451.90

Dumper 458.30 - 1378.40 reflector \$1665.60 bumper 1295

12/6/23 P/P \$11487.40 inform hui in

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐: Preli. Report☐: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech. Invs (\$ _____)☐: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNC2205G/2305065

25th May 2023

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 24th May 2023
Location : Yishun Ave 1
Name of Policyholder : Ong Kian Aik
Policy No : MA017255
Vehicle No : SNC 2205 G Lexus RX200t

not Authorised
LH
11/6/23
P/P \$ 11487.40
5 days.
Take photo before painting.
Ting H/s.

Cost Plus/ Estimated Supply of Parts & Labours

Nett item

\$ 1457.90

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover (Aluminium) <i>PO/Bent</i>	1	3,886.20	\$ 3,886.20 ✓
2	Rear boot cover emblem (logo) <i>SCA</i>	1	1,382.80	\$ 1,382.80 ✓
3	Rear boot cover reflector L&R <i>MSM 01511</i>	2	1,580.20	\$ 3,160.40 <i>IPC</i>
4	Rear number plate chrome moulding <i>garnish one</i>	1	2,346.70	\$ 2,346.70 ✓
5	Rear boot cover emblem(Lexus) <i>all</i>	1	73.70	\$ 73.70 ✓
6	Rear boot cover emblem(RX 200 t) <i>all</i>	1	95.40	\$ 95.40 ✓
7	Rear bumper fascia <i>DD</i>	1	1,233.30	\$ 1,233.30 ✓
8	Rear bumper clips <i>all</i>	1set	55.00	\$ 55.00 ✓
9	Rear bumper side retainer L&R <i>11</i>	2	148.60	\$ 297.20 X
10	Rear bumper bracket L&R <i>1A</i>	2	241.60	\$ 483.20 X
11	Rear bumper sponge <i>201</i>	1	134.40	\$ 134.40 ✓
12	Rear bumper reinforcement <i>SU</i>	1	644.30	\$ 644.30 X
13	Rear bumper sensor <i>SU</i>	2	481.90	\$ 963.80 X
14	Rear bumper diffuser <i>CUT 122</i>	1	685.90	\$ 685.90 ✓
15	Rear boot cover lock <i>SU</i>	1	1,195.00	\$ 1,195.00 X
16	Rear end panel <i>R</i>	1	1,105.00	\$ 1,105.00 X
17	Rear boot cover lower catch garnish <i>11</i>	1	825.30	\$ 825.30 X
18	Rear windscreen glass <i>11</i>	1	1,782.00	\$ 1,782.00 X
19	Rear bumper top sticker(F Sport) (s/nett) <i>NF</i>	1	380.00	\$ 380.00 X
20	Rear windscreen sealant (s/nett) <i>all</i>	2	60.00	\$ 120.00 <i>40 (S/N)</i>
				\$ 20,849.60

(102)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNC2205G/2305065

25th May 2023

Balance b/f \$ 20,849.60

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 1,080.00	500
Remove & install rear windscreen glass	\$ 140.00	120
Remove & install rear bumper sensor	\$ 100.00	50
Tuff-kote on damage parts	\$ 80.00	X
Spray painting on damage parts	\$ 1,280.00	600
Check all lighting after repairs	\$ 60.00	20
Diagnostic check & reset	\$ 300.00	X
Labour Charge	\$ 3,040.00	
Total Amount	\$ 23,889.60	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 11286.00
102
P- 10157.40
S.N-40
L- 1290
11487.40

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNC2205G/2305065

08th June 2023

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 24th May 2023
Location : Yishun Ave 1
Name of Policyholder : Ong Kian Aik
Policy No : MA017255
Vehicle No : SNC 2205 G Lexus RX200t

Supplementary of Parts

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover stopper RH <i>mis</i>	1	33.80	\$ 33.80
2	Rear boot lamp inner clip L&R <i>are</i>	2	5.50	\$ 11.00
3	Rear bumper sensor bracket <i>acc</i>	4	50.10	\$ 200.40
				<u>\$ 245.20</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.