

HENG KEE WORKSHOP

BLK 1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE S(409703)

TO	: CHINA TAIPING	DATE	: 26/5/2023
VEHICLE DETAILS			
VEHICLE NO	: GBJ964S	2019 JAN	<i>Xiao Chun</i>
VEHICLE MODEL	: TOYOTA DYNA		
CHASSIS NO	: WBA1A32040J066042		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>Ne m</i>	1	\$ 69.60	\$ 69.60
2	REAR NUMBER PLATE PANEL <i>Best.</i>	1	\$ 160.40	\$ 160.40
3	TAILLAMP <i>at</i>	1	\$ 255.40	\$ 255.40
4	TAILLAMP PANEL <i>Best</i>	1	\$ 185.50	\$ 185.50
5	STOPPER BRACKET <i>Best.</i>	1	\$ 153.20	\$ 153.20
6	TAILGATE <i>Dented</i>	1	\$ 1,482.50	\$ 1,482.50
7	TAILGATE SIDE LOCK <i>and</i>	1	\$ 160.50	\$ 160.50
8	TAILGATE HINGE <i>Best</i>	2	\$ 65.50	\$ 131.00
9	TAILGATE LOWER PANEL <i>Riv</i>	1	\$ 495.60	\$ 495.60
10	TAILGATE TOYOTA STICKER <i>Ne</i>	1	\$ 176.50	\$ 176.50
11	SIDE GATE <i>Dented</i>	1	\$ 1,881.40	\$ 1,881.40
12	SIDE GATE LOWER PANEL <i>Riv</i>	2	\$ 831.50	\$ 1,663.00
13	SPARE TYRE LOCK REGULATOR <i>new</i>	1	\$ 283.10	\$ 283.10
14	REAR EXHAUST PIPE <i>3/4</i>	1	\$ 486.50	\$ 486.50
15	REAR EXHAUST PIPE MOUNTING <i>ne</i>	1	\$ 45.10	\$ 45.10
16	REAR EXHAUST PIPE GASKET	1	\$ 32.40	\$ 32.40

458640
343980

TOTAL PRICE: \$ 7,661.70
LESS 25% \$ 1,915.42
SUB TOTAL PRICE: \$ 5,746.28

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00
2	REAR STEP PANEL <i>Best</i>	1	\$ 350.00	\$ 350.00
3	REVERSE SENSOR (SET) <i>and</i>	1	\$ 280.00	\$ 280.00
4	STOPPER <i>at</i>	1	\$ 40.00	\$ 40.00
5	TAILGATE INNER METAL PANEL <i>Dented</i>	1	\$ 380.00	\$ 380.00
6	TAILGATE INNER METAL PANEL RIVETS <i>ne</i>	1 SET	\$ 50.00	\$ 50.00
7	DYNA STICKER	1	\$ 45.00	\$ 45.00
8	70KM/H STICKER <i>3/4</i>	1	\$ 15.00	\$ 15.00
9	13 PAX STICKER	1	\$ 15.00	\$ 15.00

TOTAL: \$ 1,205.00

LABOUR

945

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	800.	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800.	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	80	
5	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
7	TO REMOVE SIDE GATE TOP RAILING	\$ 200.00	100.	

TOTAL \$ 3,250.00

1860

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,951.28

TOTAL LABOUR COST: \$ 3,250.00

TOTAL REPAIR COST: \$ 10,201.28

total: 6244.80.

h/s: 5K.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

06 Days.

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: