

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SND 8510E**
 Made : Toyota
 Model : Noah Hybrid 1.8X CVT
 Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Tailgate <i>h/</i>	1	\$ 1,812.70	\$ 1,812.70	✓
2	Rear Tailgate Outer Chrome Garnish <i>X nn</i>	1	\$ 767.80	\$ 767.80	
3	Rear Tailgate Number Plate Lamp <i>X nn</i>	2	\$ 65.40	\$ 130.80	
4	Rear Tailgate Emblem <i>X nn</i>	1	\$ 77.80	\$ 77.80	
5	Rear Tailgate "Hybrid Synergy Drive" Emblem <i>nn/</i>	1	\$ 68.20	\$ 68.20	✓
6	Rear Tailgate Inner Holder <i>X nn</i>	1	\$ 74.80	\$ 74.80	
7	Rear Tailgate Stopper <i>nn/</i>	2	\$ 28.60	\$ 57.20	✓
8	Rear Tailgate Damper RH <i>X nn</i>	1	\$ 326.80	\$ 326.80	
9	Rear Tailgate Damper LH <i>X nn</i>	1	\$ 326.80	\$ 326.80	
10	Rear Tailgate Top Lock <i>X nn</i>	1	\$ 452.60	\$ 452.60	
11	Rear Tailgate Lower Lock Striker <i>X nn</i>	1	\$ 36.70	\$ 36.70	
12	Rear Tailgate Detector <i>X nn</i>	1	\$ 195.20	\$ 195.20	
13	Rear Tailgate Detector Wire Harness <i>X nn</i>	1	\$ 307.10	\$ 307.10	
14	Rear Tailgate Buzzer <i>X nn</i>	1	\$ 112.30	\$ 112.30	
15	Rear Tailgate Inner Trim Board <i>cm/</i>	1	\$ 602.30	\$ 602.30	✓
16	Rear Tailgate Weatherstrip <i>nn</i>	1	\$ 385.10	\$ 385.10	✓
17	Rear Tailgate Windscreen Glass C/W Moulding <i>nn/</i>	1	\$ 1,308.10	\$ 1,308.10	✓
18	Rear Bumper <i>do/</i>	1	\$ 1,389.30	\$ 985 ✓ 1,389.30	
19	Rear Bumper Side Retainer RH (Front) <i>X nn</i>	1	\$ 145.80	\$ 145.80	
20	Rear Bumper Side Retainer LH (Front) <i>cm/</i>	1	\$ 145.80	\$ 145.80	✓
21	Rear Bumper Side Retainer RH (Rear) <i>X nn</i>	1	\$ 78.90	\$ 78.90	
22	Rear Bumper Side Retainer LH (Rear) <i>X nn</i>	1	\$ 78.90	\$ 78.90	
23	Rear Bumper Tow Hook Cover <i>X nn</i>	1	\$ 48.10	\$ 48.10	
24	Rear Bumper Reflector RH <i>X nn</i>	1	\$ 125.60	\$ 125.60	
25	Rear Bumper Reflector LH <i>cm/</i>	1	\$ 125.60	\$ 125.60	✓
26	Rear Bumper Upper Cover RH <i>X nn</i>	1	\$ 188.80	\$ 188.80	
27	Rear Bumper Upper Cover LH <i>cm/</i>	1	\$ 188.80	\$ 188.80	✓
28	Rear Bumper Upper Cover Retainer RH <i>X nn</i>	1	\$ 155.20	\$ 155.20	
29	Rear Bumper Upper Cover Retainer LH <i>X nn</i>	1	\$ 155.20	\$ 155.20	
30	Rear Taillamp Assembly RH <i>X nn</i>	1	\$ 685.10	\$ 685.10	
31	Rear Taillamp Assembly LH <i>X nn</i>	1	\$ 685.10	\$ 685.10	
32	Rear Taillamp Panel RH <i>X nn</i>	1	\$ 311.10	\$ 311.10	

33	Rear Taillamp Panel LH	X nn	1	\$	311.10	\$	311.10
34	Rear End Panel	LA ✓	1	\$	745.70	\$	745.70
35	Rear End Panel Extension Panel	X nn	1	\$	912.20	\$	912.20
36	Rear End Panel Top Garnish	cm ✓	1	\$	148.60	\$	148.60
37	Rear Floor Panel	X nn	1	\$	980.60	\$	980.60
38	Rear Floor Panel Top Board	X nn	1	\$	1,105.50	\$	1,105.50
39	Rear Floor Panel Top Board Inner Support	X nn	1	\$	879.20	\$	879.20
40	Rear Floor Mat	X nn	1	\$	685.10	\$	685.10
41	Jack Cover Garnish	X nn	1	\$	186.00	\$	186.00
42	Battery Cover Garnish	X nn	1	\$	240.00	\$	240.00
43	Rear Fender RH	X nn	1	\$	1,340.60	\$	1,340.60
44	Rear Fender LH	X nn	1	\$	1,340.60	\$	1,340.60
45	Rear Fender Glass RH	X nn	1	\$	689.90	\$	689.90
46	Rear Fender Glass LH	X nn	1	\$	689.90	\$	689.90
47	Rear Fender Glass Moulding RH	X nn	1	\$	190.54	\$	190.54
48	Rear Fender Glass Moulding LH	X nn	1	\$	190.54	\$	190.54
49	Rear Fender Inner Trim RH	X nn	1	\$	906.60	\$	906.60
50	Rear Fender Inner Trim LH	sent ✓	1	\$	906.60	\$	906.60
51	Rear Air Con Blower Motor	X nn	1	\$	3,294.00	\$	3,294.00
52	Rear Fender Inner Shield RH	X nn	1	\$	260.00	\$	260.00
53	Rear Fender Inner Shield LH	X nn	1	\$	260.00	\$	260.00
				7479.70	Parts Sub Total :	\$	27,812.88
				-25%	Discount	\$	6,953.22
				5609.77	25%	PARTS TOTAL :	\$ 20,859.66

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate X nn	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set m /	1	\$ 50.00	\$ 30 50.00
3	Rear Tailgate Outer Garnish Chrome Clips - Set X nn	1	\$ 30.00	\$ X 30.00
4	Rear Tailgate Inner Trim Board Clips - Set m /	1	\$ 40.00	\$ 30 40.00
5	Rear End Panel Top Garnish Clips - Set m /	1	\$ 40.00	\$ 20 40.00
6	Rear Fender Inner Trim Clips - Set X nn	2	\$ 40.00	\$ X 80.00
7	Rear Fender Inner Shield Clips - Set X nn	2	\$ 30.00	\$ X 60.00
8	Rear Tailgate Windscreen Glass Sealant m /	1	\$ 150.00	\$ 60 150.00
9	Rear Tailgate Windscreen Glass Solar Film X nn	1	\$ 500.00	\$ X 500.00
10	Rear Fender Glass Sealant X nn	2	\$ 100.00	\$ X 200.00
11	Rear Fender Glass Solar Film X nn	2	\$ 250.00	\$ X 500.00
12	Rear Tailgate Sealant X nn	1	\$ 150.00	\$ X 150.00
13	Rear End Panel Sealant m /	1	\$ 150.00	\$ 40 150.00
14	Rear Floor Panel Sealant X nn	1	\$ 150.00	\$ X 150.00
15	Rear Fender RH Sealant X nn	1	\$ 150.00	\$ X 150.00
16	Rear Fender LH Sealant X nn	1	\$ 150.00	\$ X 150.00
17	Rear Tailgate Reverse Camera X nn	1	\$ 550.00	\$ X 550.00
18	Rear Bumper Reverse Sensor - Set X nn	1	\$ 250.00	\$ X 250.00
				SPECIAL NETT TOTAL : \$ 3,250.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 650 2,400.00
2	To Spray Paint Affected Areas	\$ 650 2,000.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 1,200 150.00
5	To Remove & Refix Rear Fender Glass	\$ X 120.00
6	To Transfer Rear Tailgate Mechanism	\$ 60 150.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 400 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 40 120.00
9	To Remove & Refix Rear Exhaust Pipe	\$ X 150.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 150.00
11	To Remove & Refix Fuel Tank to facilitate repairs	\$ X 150.00
12	To apply anti rust on affected parts	\$ 60 250.00
13	To Conduct Water Leak Test	\$ 30 100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 100 480.00
1710 LABOUR TOTAL :		\$ 6,470.00

7499.77

L/S - 5999.81
= 6000

PARTS TOTAL : \$ 20,859.66

SPECIAL NETT TOTAL : \$ 3,250.00

LABOUR TOTAL : \$ 6,470.00

GRAND TOTAL : \$ 30,579.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rashid
Hp 90010068
7 days
L/S
26/05/23 @ 1145
Resurvey after repair