

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SND 8510E
at Workshop m/s BIFROST AUTO P/L
of 81 KKKI BUKIT ARK 4 #01-49
Insured: SJW 3450A CTI
Policy No. DMPCSNW00229092200
Chassis No. SNM23D203721/C02/LEWLC
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 186K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SND 8510E Yr Regn: 2022 / JAN
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA NOAH HYBRID 1.8X c.c. 1797
Colour: GREY A/C: Insured / Std / NI / NA
Sp. Reading: 96308 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZWR806584109
Gen. Cond: Good / Fair / Poor
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or I-PLUS
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 23/08/23 D.O.I. 26/05/23
Survey held at BIFROST
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 102K

14/7/23 Lump Sum \$6000 confirmed by email (Red 24,579.66, 80%)

Date/Time, File Pass to?

☐
☐

Prell. Report

Final Report

1)

Date/Time, File Return to?

2) 14/7/23-typist

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐
☐
☐
☐

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / L.B. (\$ 6000)

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SND 8510E**
Made : Toyota
Model : Noah Hybrid 1.8X CVT
Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate <i>h/</i>	1	\$ 1,812.70	\$ 1,812.70
2	Rear Tailgate Outer Chrome Garnish <i>X</i>	1	\$ 767.80	\$ 767.80
3	Rear Tailgate Number Plate Lamp <i>X</i>	2	\$ 65.40	\$ 130.80
4	Rear Tailgate Emblem <i>X</i>	1	\$ 77.80	\$ 77.80
5	Rear Tailgate "Hybrid Synergy Drive" Emblem <i>nh/</i>	1	\$ 68.20	\$ 68.20
6	Rear Tailgate Inner Holder <i>X</i>	1	\$ 74.80	\$ 74.80
7	Rear Tailgate Stopper <i>m/</i>	2	\$ 28.60	\$ 57.20
8	Rear Tailgate Damper RH <i>X</i>	1	\$ 326.80	\$ 326.80
9	Rear Tailgate Damper LH <i>X</i>	1	\$ 326.80	\$ 326.80
10	Rear Tailgate Top Lock <i>X</i>	1	\$ 452.60	\$ 452.60
11	Rear Tailgate Lower Lock Striker <i>X</i>	1	\$ 36.70	\$ 36.70
12	Rear Tailgate Detector <i>X</i>	1	\$ 195.20	\$ 195.20
13	Rear Tailgate Detector Wire Harness <i>X</i>	1	\$ 307.10	\$ 307.10
14	Rear Tailgate Buzzer <i>X</i>	1	\$ 112.30	\$ 112.30
15	Rear Tailgate Inner Trim Board <i>cm/</i>	1	\$ 602.30	\$ 602.30
16	Rear Tailgate Weatherstrip <i>m</i>	1	\$ 385.10	\$ 385.10
17	Rear Tailgate Windscreen Glass C/W Moulding <i>m/</i>	1	\$ 1,308.10	\$ 1,308.10
18	Rear Bumper <i>do/</i>	1	\$ 1,389.30	\$ 1,389.30
19	Rear Bumper Side Retainer RH (Front) <i>X</i>	1	\$ 145.80	\$ 145.80
20	Rear Bumper Side Retainer LH (Front) <i>cm/</i>	1	\$ 145.80	\$ 145.80
21	Rear Bumper Side Retainer RH (Rear) <i>X</i>	1	\$ 78.90	\$ 78.90
22	Rear Bumper Side Retainer LH (Rear) <i>X</i>	1	\$ 78.90	\$ 78.90
23	Rear Bumper Tow Hook Cover <i>X</i>	1	\$ 48.10	\$ 48.10
24	Rear Bumper Reflector RH <i>X</i>	1	\$ 125.60	\$ 125.60
25	Rear Bumper Reflector LH <i>cm/</i>	1	\$ 125.60	\$ 125.60
26	Rear Bumper Upper Cover RH <i>X</i>	1	\$ 188.80	\$ 188.80
27	Rear Bumper Upper Cover LH <i>cm/</i>	1	\$ 188.80	\$ 188.80
28	Rear Bumper Upper Cover Retainer RH <i>X</i>	1	\$ 155.20	\$ 155.20
29	Rear Bumper Upper Cover Retainer LH <i>X</i>	1	\$ 155.20	\$ 155.20
30	Rear Taillamp Assembly RH <i>X</i>	1	\$ 685.10	\$ 685.10
31	Rear Taillamp Assembly LH <i>X</i>	1	\$ 685.10	\$ 685.10
32	Rear Taillamp Panel RH <i>X</i>	1	\$ 311.10	\$ 311.10

33	Rear Taillamp Panel LH <i>X</i>	1	\$	311.10	\$	311.10
34	Rear End Panel <i>LA</i>	1	\$	745.70	\$	745.70
35	Rear End Panel Extension Panel <i>X</i>	1	\$	912.20	\$	912.20
36	Rear End Panel Top Garnish <i>cm</i>	1	\$	148.60	\$	148.60
37	Rear Floor Panel <i>X</i>	1	\$	980.60	\$	980.60
38	Rear Floor Panel Top Board <i>X</i>	1	\$	1,105.50	\$	1,105.50
39	Rear Floor Panel Top Board Inner Support <i>X</i>	1	\$	879.20	\$	879.20
40	Rear Floor Mat <i>X</i>	1	\$	685.10	\$	685.10
41	Jack Cover Garnish <i>X</i>	1	\$	186.00	\$	186.00
42	Battery Cover Garnish <i>X</i>	1	\$	240.00	\$	240.00
43	Rear Fender RH <i>X</i>	1	\$	1,340.60	\$	1,340.60
44	Rear Fender LH <i>X</i>	1	\$	1,340.60	\$	1,340.60
45	Rear Fender Glass RH <i>X</i>	1	\$	689.90	\$	689.90
46	Rear Fender Glass LH <i>X</i>	1	\$	689.90	\$	689.90
47	Rear Fender Glass Moulding RH <i>X</i>	1	\$	190.54	\$	190.54
48	Rear Fender Glass Moulding LH <i>X</i>	1	\$	190.54	\$	190.54
49	Rear Fender Inner Trim RH <i>X</i>	1	\$	906.60	\$	906.60
50	Rear Fender Inner Trim LH <i>sent</i>	1	\$	906.60	\$	906.60
51	Rear Air Con Blower Motor <i>X</i>	1	\$	3,294.00	\$	3,294.00
52	Rear Fender Inner Shield RH <i>X</i>	1	\$	260.00	\$	260.00
53	Rear Fender Inner Shield LH <i>X</i>	1	\$	260.00	\$	260.00

Parts Sub Total : \$ 27,812.88

25% Discount \$ 6,953.22

PARTS TOTAL : \$ 20,859.66

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate <i>X</i>	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set <i>m</i>	1	\$ 50.00	\$ 50.00 30
3	Rear Tailgate Outer Garnish Chrome Clips - Set <i>X</i>	1	\$ 30.00	\$ 30.00 X
4	Rear Tailgate Inner Trim Board Clips - Set <i>m</i>	1	\$ 40.00	\$ 40.00 30
5	Rear End Panel Top Garnish Clips - Set <i>m</i>	1	\$ 40.00	\$ 40.00 20
6	Rear Fender Inner Trim Clips - Set <i>X</i>	2	\$ 40.00	\$ 80.00 X
7	Rear Fender Inner Shield Clips - Set <i>X</i>	2	\$ 30.00	\$ 60.00 X
8	Rear Tailgate Windscreen Glass Sealant <i>m</i>	1	\$ 150.00	\$ 150.00 60
9	Rear Tailgate Windscreen Glass Solar Film <i>X</i>	1	\$ 500.00	\$ 500.00 X
10	Rear Fender Glass Sealant <i>X</i>	2	\$ 100.00	\$ 200.00 X
11	Rear Fender Glass Solar Film <i>X</i>	2	\$ 250.00	\$ 500.00 X
12	Rear Tailgate Sealant <i>X</i>	1	\$ 150.00	\$ 150.00 X
13	Rear End Panel Sealant <i>m</i>	1	\$ 150.00	\$ 150.00 40
14	Rear Floor Panel Sealant <i>X</i>	1	\$ 150.00	\$ 150.00 X
15	Rear Fender RH Sealant <i>X</i>	1	\$ 150.00	\$ 150.00 X
16	Rear Fender LH Sealant <i>X</i>	1	\$ 150.00	\$ 150.00 X
17	Rear Tailgate Reverse Camera <i>X</i>	1	\$ 550.00	\$ 550.00 X
18	Rear Bumper Reverse Sensor - Set <i>X</i>	1	\$ 250.00	\$ 250.00 X
SPECIAL NETT TOTAL :				\$ 3,250.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 650 2,400.00
2	To Spray Paint Affected Areas	\$ 650 2,000.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 1,200 150.00
5	To Remove & Refix Rear Fender Glass	\$ X 120.00
6	To Transfer Rear Tailgate Mechanism	\$ 60 150.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 400 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 40 120.00
9	To Remove & Refix Rear Exhaust Pipe	\$ X 150.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 150.00
11	To Remove & Refix Fuel Tank to facilitate repairs	\$ X 150.00
12	To apply anti rust on affected parts	\$ 60 250.00
13	To Conduct Water Leak Test	\$ 30 100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 100 480.00
LABOUR TOTAL :		\$ 6,470.00

PARTS TOTAL : \$ 20,859.66
SPECIAL NETT TOTAL : \$ 3,250.00
LABOUR TOTAL : \$ 6,470.00
GRAND TOTAL : \$ 30,579.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rashid
Hp 90010068
7 days
L/S
26/05/23 @ 1145
Repair after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	
Owner ID:	Company
Vehicle Details	343K
Vehicle No.:	
Vehicle to be Exported:	SND8510E
Intended Deregistration Date:	Yes
Vehicle Make:	24 May 2023
Vehicle Model:	TOYOTA
Primary Colour:	NOAH HYBRID 1.8X
Manufacturing Year:	Brown
Engine No.:	2021
Chassis No.:	2ZR2M70428
Maximum Power Output:	ZWR800504109
Open Market Value:	100.0 kW (134 bhp)
Original Registration Date:	\$33,701.00
First Registration Date:	27 Jan 2022
Transfer Count:	27 Jan 2022
Actual ARF Paid:	0
Intended PARF Rebate Details	\$24,182.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2032
PARF Rebate Amount:	\$18,136.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2032
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$82,001.00
COE Rebate Amount:	\$65,600.00
Total Rebate Amount:	\$83,736.00

The information contained herein is correct as at 24 May 2023

OK

Toyota Noah Hybrid 1.8A X

\$190,800 Instalment \$1,647/mth

PREMIUM AD

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	i \$20,280 / year
Reg. Date	29-Mar-2022 (8yrs 10mths COE left)
Manufactured	i 2021
Mileage	13,674 km (11.7k / year)
Transmission	Auto
Engine Cap	1,797 cc
Road Tax	i \$974 / year
Power	100.0 kW (134 bhp) View specs of the Toyota Noah
Curb Weight	i 1,610 kg
Fuel Type	Petrol-Electric
COE	i \$98,890
OMV	i \$32,806
ARF	i \$22,929
Dereg Value	i \$92,225 as of today