

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 24.05.23
 MODEL: Hyundai i40
 VEHICLE NO.: SHB4157A

INSURANCE: ALLIANZ
 MVA: JUMANI

D.O.A 14.05.23

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	REAR DOOR ASSY LH			\$2,201.10	By
	REAR FENDER LH			\$2,171.40	By
	ROCKER PANEL GARNISH RH			\$732.80	By
	REAR WHEEL RIM CAP			\$217.20	Out
	REAR BUMPER ASSY			\$553.00	By
	SUB TOTAL		217.20	\$5,875.50	
	LESS 25%			\$1,468.87	
	DISCOUNTED TOTAL		20% - 173.76	\$4,406.63	
	ADVERTISEMENT LOGO - 4 PCS			\$400.00	NET
	REAR DOOR APPS LOGO			\$80.00	NET
	FRT DOOR COMFORT LOGO			\$75.00	NET
				\$555.00	
	<u>Labour Charge</u>				
	<u>PANEL BEATING</u>			1200	560
	<u>SPRAYPAINT</u>			\$1,200.00	1100
	<u>WIRING CHARGES</u>			\$50.00	x 7
	<u>TUFF KOTE</u>			\$50.00	x 7
	<u>REMOVE/REFIX DOOR PARTS</u>			\$120.00	x 7
	TOTAL LABOUR		2388.70	\$ 2,620.00	
	ESTIMATE TOTAL		45\$1600	\$ 7,581.63	
			- 3 days		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97495749
 'w' 25/5/23 1pm
 4/3 Repair after repair
 Tanjin e/Manuf.com
 03 days
 Repair Limit \$1600

- Auto Consultants** hence forth
 the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without-repair" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date: