

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	BLUWEL AUTOMO	TIVE SERVICE PTE LTD	Ref:	CS/TP23005333/Unp3e2	
	BLK 1 KAKI BUKIT #01-28/53/55/56 (N 417883	AVE 6 IAIN OFFICE)SINGAPORE	Date:	09/06/2023	
	ON BEHALF OF RI	EIN SERVICES	Code:	TP149	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SKP 4644B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	25/05/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF A7 1.4 (A)	c.c	1395	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WVWZZZAUZFW009466	Colour	SILVER	
	Odometer	167114 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40Z R18	TOURADOR	7 mm	
	L/H Front Tyre	225/40Z R18	TOURADOR	7 mm	
	R/H Rear Tyre	225/40Z R18	TOURADOR	7 mm	
	L/H Rear Tyre	225/40Z R18	TOURADOR	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/05/2023	Inspection Date	25/05/2023	
	Survey held at BLUWEL AUTOMOTIVE SERVICE PL				
		BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				