



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 24-05-2023

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

VEHICLE NO. : GBJ1820S

ACCIDENT DATE : 22-05-2023 15:00

THIRD PARTY REF. : SBH8899E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE GBJ1820S MITSUBISHI CANTER FEA01BR2SDEK (CBU)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN GLASS	530.00
2	1	FRONT WINDSCREEN RUBBER	200.00
3	1	FRONT WINDSCREEN PILLAR RH	650.00
4	1	FRONT WINDSCREEN PILLAR OUTER RH	450.00
5	1	FRONT WINDSCREEN PILLAR INNER RH	350.00
6	1	FRONT WINDSCREEN INNER GARNISH RH	145.00
7	1	FRONT BODY FAME RUBBER RH	150.00
8	1	REAR FENDER RH	980.00
9	1	FRONT PANEL	580.00
10	1	FRONT PANEL FUSO EMBLEM	100.00
11	1	FRONT WIPER PANEL	450.00
12	2	FRONT WIPER ARM@\$80.00	160.00
13	2	FRONT WIPER BLADE@\$35.00	70.00
14	1	FRONT GRILLE	580.00
15	1	FRONT GRILLE EMBLEM	80.00
16	1	FRONT GRILLE CANTER EMBLEM	75.00
17	1	FRONT GRILLE BRACKET	75.00
18	8	FRONT GRILLE CLIP@\$2.50	20.00
19	2	FRONT HEADLAMP@\$420.00	840.00
20	2	FRONT HEADLAMP LOWER RUBBER@\$45.00	90.00
21	1	FRONT SIDE LAMP RH	155.00
22	1	FRONT SIGALLAMP RH	180.00
23	1	FRONT BUMPER	650.00
24	2	FRONT BUMPER RUBBER@\$300.00	600.00
25	2	FRONT BUMPER BRACKET@\$95.00	190.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	2	FRONT BUMPER INNER BRACKET@\$78.00	156.00
27	1	FRONT CORNER PANEL RH	320.00
28	1	FRONT CORNER PANEL TOP GARNISH RH	40.00
29	1	FRONT SIDE MIRROR RH	250.00
30	1	DASHBAORD	1080.00
31	1	DASHBOARD REINFORCEMENT	850.00
32	1	DASHBOARD METER CASING	285.00
33	1	DASHBOARD CENTRE CONSOLE	380.00
34	1	FRONT STEP GARNISH RH	260.00
35	1	FRONT STEP PANEL INNER RH	385.00
36	1	WHEEL ARCH PANEL RH	325.00
37	1	WHEEL ARCH GARNISH RH	235.00
38	1	FRONT DOOR RH	900.00
39	1	FRONT DOOR HINGE TOP RH	65.00
40	1	FRONT DOOR HINGE LOWER RH	65.00
41	1	FRONT DOOR CHECKER RH	75.00
42	1	FRONT DOOR GLASS RH	350.00
43	1	FRPMT DOOR GLASS STAND RH	75.00
44	1	FRONT DOOR RUN CHANNEL RH	108.00
45	1	FRONT DOOR OUTER MOUDLING RH	125.00
46	1	FRONT DOOR 1/4 GARNISH RH	65.00
47	1	FRONT DOOR LOCK RH	150.00
48	1	FRONT DOOR RUBBER RH	145.00
49	1	FRONT DOOR REGULATOR RH	280.00
50	1	FRONT DOOR REGULATOR MOTOR RH	420.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
51	1	FRONT DOOR TRIMBOARD RH	650.00
52	1	FRONT DOOR COIN BOX RH	108.00
53	1	FRONT DOOR TRIMBOARD TOP RH	265.00
54	1	FRONT DOOR AIR VENT RH	75.00
55	1	FRONT DOOR POWER SWITCH RH	155.00
56	1	FRONT DOOR LOWER GARNISH RH	220.00
57	1	RADIATOR	780.00
58	1	RADIATOR FAN COWLING	255.00
59	1	RADIATOR FAN BLADE	180.00
60	1	FAN CLUTCH	450.00
61	1	ENGINE MOUNTING RH	180.00
62	1	ENGINE MOUNTING LH	180.00
63	1	ENGINE MOUNTING RR	180.00
64	1	ENGINE MOUNTING FRT	180.00
65	1	AIR CON BLOWER	1550.00
66	1	HEATER UNIT	980.00
67	1	FRONT CABIN BAR	780.00
68	2	FRONT CABIN BAR BRACKET@\$480.00	960.00
69	2	FRONT CABIN SEAL @\$125.00	250.00
70	1	STEERING BOX	0.00
71	1	STEERING SHAFT	0.00
72	1	STEERING COUPLING	0.00
73	1	BRAKE BOOSTER	0.00
74	1	BRAKE MASTER PUMP	0.00
75	1	CLUTCH PUMP	0.00



簡福星摩王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
			24,117.00
		ADD 10 %	2,411.70
		TOTAL (A)	26,528.70
SPECIAL NETT ITEMS			
1	1	FRONT NUMBER PLATE	40.00
		TOTAL (C)	40.00
LABOUR CHARGES			
1	1	TO CHECK WIRING SYSTEM	100.00
2	1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	120.00
3	1	TO REMOVE/REFIT DASHBOARD	280.00
4	1	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	180.00
5	1	TO REMOVE/REFIT CUSHION CARPET AND ETC	220.00
6	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	1080.00
7	1	SPRAYPAINTING CHARGES	1000.00
		TOTAL (D)	2,980.00
		ESTIMATE TOTAL	29,548.70

* Panel:- by the oil leak
after the accident *