



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 24-05-2023

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : GBJ1820S

ACCIDENT DATE : 22-05-2023 15:00

THIRD PARTY REF. : SBH8899E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE GBJ1820S MITSUBISHI CANTER FEA01BR2SDEK (CBU)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN GLASS	530.00 <i>can</i>
2	1	FRONT WINDSCREEN RUBBER	200.00 <i>net</i>
3	1	FRONT WINDSCREEN PILLAR RH	650.00 ?
4	1	FRONT WINDSCREEN PILLAR OUTER RH	450.00 ?
5	1	FRONT WINDSCREEN PILLAR INNER RH	350.00 <i>Rx</i>
6	1	FRONT WINDSCREEN INNER GARNISH RH	145.00 <i>de</i>
7	1	FRONT BODY FAME RUBBER RH	150.00 ?
8	1	REAR FENDER RH	980.00 <i>Rx</i>
9	1	FRONT PANEL	580.00 <i>bt</i>
10	1	FRONT PANEL FUSO EMBLEM	100.00 <i>ne</i>
11	1	FRONT WIPER PANEL	450.00 <i>can</i>
12	2	FRONT WIPER ARM@\$80.00	160.00 x
13	2	FRONT WIPER BLADE@\$35.00	70.00 x
14	1	FRONT GRILLE	580.00 <i>can</i>
15	1	FRONT GRILLE EMBLEM	80.00 <i>ng</i>
16	1	FRONT GRILLE CANTER EMBLEM	75.00 <i>ne</i>
17	1	FRONT GRILLE BRACKET	75.00 <i>ds</i>
18	8	FRONT GRILLE CLIP@\$2.50	20.00 <i>net</i>
19	2	FRONT HEADLAMP@\$420.00	LHX 840.00 <i>RH can</i>
20	2	FRONT HEADLAMP LOWER RUBBER@\$45.00	LHX 90.00 <i>RH ds</i>
21	1	FRONT SIDE LAMP RH	155.00 <i>can</i>
22	1	FRONT SIGALLAMP RH	180.00 <i>can</i>
23	1	FRONT BUMPER	650.00 <i>bt</i>
24	2	FRONT BUMPER RUBBER@\$300.00	LHX 600.00 <i>RH ?</i>
25	2	FRONT BUMPER BRACKET@\$95.00	LHX 190.00 <i>RH ?</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	2	FRONT BUMPER INNER BRACKET@\$78.00	156.00 RH?
27	1	FRONT CORNER PANEL RH	320.00 cug✓
28	1	FRONT CORNER PANEL TOP GARNISH RH	40.00 mil✓
29	1	FRONT SIDE MIRROR RH	250.00 dis✓
30	1	DASHBAORD	1080.00 ?
31	1	DASHBOARD REINFORCEMENT	850.00 ?
32	1	DASHBOARD METER CASING	285.00 ?
33	1	DASHBOARD CENTRE CONSOLE	380.00 ?
34	1	FRONT STEP GARNISH RH	260.00 cug✓
35	1	FRONT STEP PANEL INNER RH	385.00 ?
36	1	WHEEL ARCH PANEL RH	325.00 Ry
37	1	WHEEL ARCH GARNISH RH	235.00 ?
38	1	FRONT DOOR RH	900.00 bt✓
39	1	FRONT DOOR HINGE TOP RH	65.00 bt✓
40	1	FRONT DOOR HINGE LOWER RH	65.00 bt✓
41	1	FRONT DOOR CHECKER RH	75.00 ?
42	1	FRONT DOOR GLASS RH	350.00 bro✓
43	1	FRPMT DOOR GLASS STAND RH	75.00 bt✓
44	1	FRONT DOOR RUN CHANNEL RH	108.00 de✓
45	1	FRONT DOOR OUTER MOUDLING RH	125.00 de✓
46	1	FRONT DOOR 1/4 GARNISH RH	65.00 cug✓
47	1	FRONT DOOR LOCK RH	150.00 jm✓
48	1	FRONT DOOR RUBBER RH	145.00 und✓
49	1	FRONT DOOR REGULATOR RH	280.00 ?
50	1	FRONT DOOR REGULATOR MOTOR RH	420.00 ?



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
51	1	FRONT DOOR TRIMBOARD RH	650.00 <i>de</i>
52	1	FRONT DOOR COIN BOX RH	108.00 ?
53	1	FRONT DOOR TRIMBOARD TOP RH	265.00 <i>de</i>
54	1	FRONT DOOR AIR VENT RH	75.00 ?
55	1	FRONT DOOR POWER SWITCH RH	155.00 ?
56	1	FRONT DOOR LOWER GARNISH RH	220.00 ?
57	1	RADIATOR	780.00 ?
58	1	RADIATOR FAN COWLING	255.00 ?
59	1	RADIATOR FAN BLADE	180.00 ?
60	1	FAN CLUTCH	450.00 ?
61	1	ENGINE MOUNTING RH	180.00 ?
62	1	ENGINE MOUNTING LH	180.00 ?
63	1	ENGINE MOUNTING RR	180.00 ?
64	1	ENGINE MOUNTING FRT	180.00 ?
65	1	AIR CON BLOWER	1550.00 ?
66	1	HEATER UNIT	980.00 ?
67	1	FRONT CABIN BAR	780.00 ?
68	2	FRONT CABIN BAR BRACKET@\$480.00	960.00 ?
69	2	FRONT CABIN SEAL @\$125.00	250.00 ?
70	1	STEERING BOX	0.00 ?
71	1	STEERING SHAFT	0.00 ?
72	1	STEERING COUPLING	0.00 ?
73	1	BRAKE BOOSTER	0.00 ?
74	1	BRAKE MASTER PUMP	0.00 ?
75	1	CLUTCH PUMP	0.00 ?



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBJ1820S
ACCIDENT DATE : 22-05-2023 15:00
THIRD PARTY REF. : SBH8899E

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

ADD 10 %

TOTAL (A)

24,117.00

2,411.70

26,528.70

SPECIAL NETT ITEMS

1 1 FRONT NUMBER PLATE

TOTAL (C)

40.00 H-

40.00

LABOUR CHARGES

1 1 TO CHECK WIRING SYSTEM

2 1 TO REMOVE/REFIT FRONT WINDSCREEN GLASS

3 1 TO REMOVE/REFIT DASHBOARD

4 1 TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS

5 1 TO REMOVE/REFIT CUSHION CARPET AND ETC

6 1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

7 1 SPRAYPAINTING CHARGES

TOTAL (D)

ESTIMATE TOTAL

100.00 40

120.00 ✓

280.00 200? plate

180.00 ?

220.00 100

1080.00 900

1000.00 900

2,980.00

29,548.70

* Panel:- Bigger oil leak
after the accident
Taufik 97495749 / 62563561
Not Authorise 25/5/23 R 1115
Exit to be advise
taufik@kkhauto.com 10 days.
L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____