

## Vehicle Damage Assessment Report for [GBK3475L]

Estimate Created: 14/06/2023 01:50 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

Owned: 14/06/2023 02:02 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | ERGO                         | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |       |
|----------------------|----------|--------------------|-------|
| Brand                | Suzuki   | Model              | Every |
| Engine Type          |          |                    |       |
| License Plate Number | GBK3475L | VIN (or Chassis #) |       |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$4,600.00 AND 4 WORKING  
DAYS.

Insurlogic 4 (14/06/2023 02:02)

**Parts**

| Description               | Number/Type | Qty | Cost    | Markup/Disc.% | Sum      |
|---------------------------|-------------|-----|---------|---------------|----------|
| Tailgate                  |             | 1   | 1820.00 | -5.00 %       | 1,729.00 |
| Rear bumper               |             | 1   | 845.00  | -5.00 %       | 802.75   |
| Rear bumper lamps o/s     |             | 1   | 299.00  | -5.00 %       | 284.05   |
| Rear bumper side retainer |             | 2   | 65.00   | -5.00 %       | 123.50   |

Parts Subtotal 2,939.30

**Materials**

| Description                     | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|---------------------------------|-------------|-----|--------|---------------|--------|
| Rear windscreen sealant         |             | 1.0 | 40.00  | 0.00 %        | 40.00  |
| Rear windscreen inner seal      |             | 1.0 | 40.00  | 0.00 %        | 40.00  |
| Tailgate 70KM/H sticker         |             | 1.0 | 10.00  | 0.00 %        | 10.00  |
| Tailgate sealant                |             | 1.0 | 50.00  | 0.00 %        | 50.00  |
| Tailgate Matt sticker           |             | 1.0 | 300.00 | 0.00 %        | 300.00 |
| Tailgate rear corporate sticker |             | 1.0 | 500.00 | 0.00 %        | 500.00 |
| Rear bumper matt sticker        |             | 1.0 | 300.00 | 0.00 %        | 300.00 |
| Rear bumper clips               |             | 1.0 | 50.00  | 0.00 %        | 50.00  |
| Rear bumper reverse sensor      |             | 1.0 | 200.00 | 0.00 %        | 200.00 |

Materials Subtotal 1,490.00

**Labor****Replace/RnR**

| Description                             | Type | Cost   | Markup/Disc % | Price  |
|-----------------------------------------|------|--------|---------------|--------|
| To remove and refit rear reverse sensor | RnR  | 50.00  | 0.00 %        | 50.00  |
| To remove and refit rear windscreen.    | RnR  | 100.00 | 0.00 %        | 100.00 |
| To check wiring                         | RnR  | 20.00  | 0.00 %        | 20.00  |
| To remove and refit tailgate mechanism  | RnR  | 60.00  | 0.00 %        | 60.00  |
| To spray rust proofing                  | RnR  | 30.00  | 0.00 %        | 30.00  |
| Panel bearing                           | RnR  | 400.00 | 0.00 %        | 400.00 |

**Paint**

| Description    | Paint Type | Cost   | Markup/Disc % | Price  |
|----------------|------------|--------|---------------|--------|
| Spray painting | Full spray | 680.00 | 0.00 %        | 680.00 |

|            |               |                        |          |
|------------|---------------|------------------------|----------|
| Labor Rate | S\$ 50 / Hour | General Labor Subtotal | 660.00   |
|            |               | Paint Labor Subtotal   | 680.00   |
|            |               | Labor Subtotal         | 1,340.00 |

Summary

|                |            |
|----------------|------------|
| Repair Cost    | 5,769.30   |
| Discount(20 %) | (1,153.86) |
|                | 4,615.44   |
| Excess         | (0.00)     |
| GST(0.00 %)    | 0.00       |
| Grand Subtotal | 4,615.44   |