

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EG/23005345/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBK3475C

at Workshop m/s

RP

of

Insured:

SKR 4833C

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$52k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

3137C

Vehicle: IN / OUT

Date:

Person Contacted:

L7A615401

Veh No:

GBK3475C

Yr Regn:

26/25/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Suzuki Every

c.c

658

Colour

multicolour

A/C

Insured / Std / NI / NA

Sp. Reading

60800

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

DA17V 854815

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

15.5-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ZB Ukan

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/25/23

D.O.I.

25/25/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 7500

have video of fold

have wrop st. clear cost \$800

Tailgate silver colour

8/6/23 L/S #4600 inland Alan. (Ref # 9173-90, 67%)

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

4

1)



Final Report

Resurvey No. of Trip:

3

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

4600

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Available
25/5/23
2/5/24 4600
4 days

VEHICLE No: GBK 3475L

NETT ITEM

1PC	TAILGATE	body
1PC	TAILGATE REAR LOGO	NT
1PC	TAILGATE 'EVERY' STICKER	NT
1PC	TAILGATE INNER LOCK	11
1PC	TAILGATE INNER TRIM	11
1PC	TAILGATE INNER PULL GARNISH	11
1PC	TAILGATE OUTER HANDLE	11
1PC	REAR BUMPER	11/2e
2PCS	REAR BUMPER LAMPS @\$320.00	MS 11 0/5 one
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11
1PC	REAR BUMPER UNDER SHIELD N/S	11
1PC	REAR END PANEL OUTER	11
1PC	REAR END PANEL INNER	11
1PC	REAR EXHAUST	11
1PC	REAR SPARE TYRE BRACKET	11

1820	\$1,920.00
	\$92.00 X
	\$80.00 X
	\$295.00 X
	\$399.00 X
	\$98.00 X
	\$420.00 X
845	\$1,120.00
299	\$640.00 100
	\$130.00
	\$168.00 X
	\$566.00 X
	\$595.00 X
	\$588.00 X
	\$291.00 X
	\$7,402.00
LESS 5%	\$7,563.90

S.NETT

1PC	REAR WINDSCREEN SEALANT	11
1PC	REAR WINDSCREEN INNER SEAL	11
1PC	TAILGATE 70km/h STICKER	11
1PC	TAILGATE SEALANT	11
1SET	TAILGATE INNER TRIM BOARD CLIPS	11
1SET	TAILGATE MATT STICKER	11
1SET	TAILGATE REAR CORPORATE STICKER	11
1SET	REAR BUMPER MATT STICKER	11
1SET	REAR BUMPER CLIPS	11
1SET	REAR FENDER MATT STICKER O/S	11
1SET	REAR O/S STICKER DECAL	11
1PC	REAR END PANEL SEALANT	11
1SET	REAR BUMPER REVERSE SENSOR	no function

5/12	\$40.00
	\$40.00
	\$10.00
	\$50.00
	\$50.00 X
	\$500.00 300
	\$1,200.00 500
	\$500.00 300
	\$50.00
	\$800.00 X
	\$50.00 X
	\$80.00 X
	\$250.00 200

TO CHECK WIRING	\$50.00 20
TO R&R REAR REVERSE SENSOR	\$80.00 50
TO R&R REAR WINDSCREEN	\$120.00 100
TO R&R TAILGATE MECHANISM	\$100.00 60
TO R&R CUSHION UPHOLSTERY	11 \$120.00 X
TO R&R REAR EXHAUST	11 \$100.00 X
TO DIAGNOSTIC & REPROGRAMME SYSTEM	11 \$120.00 X

TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$100.00	30
	\$800.00	400
	\$1,000.00	680
TOTAL	\$13,773.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2- 3094
52
2939.3
1490
1340
5789.3
202
4615