

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 May 2023

Preliminary Advice

Vehicle No	: YN9985D	Accident Date	: 23/05/2023
Make	: ISUZU NPR85UH5A	Policy No.	: DMCG22015494
Assignment Date	: 30/05/2023	Excess	: S\$0.00
Date of Inspection	: 26/05/2023	Est. Duration of Repair	: 14
Inspection At	: JIT KEONG TRADING CO. PTE LTD (HQ) 28 BENOI PLACE SINGAPORE 629945		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,447.00
Revised Amount	:S\$	13,907.00
Check Items (Estimated)	:S\$	525.00
Total	:S\$	14,432.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	10,708.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,292.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.